

CareFusion Switzerland 317 Sàrl A-One Business Centre Zone d'activités, Vers-la-Pièce No 10 Rolle, CH-1180 Switzerland

carefusion.com

Customer Name Address

URGENT FIELD SAFETY NOTICE

Product Name: Secondary Sets containing Back Check Valve

Product codes: 72951NE, 72947NE, 72948NE, 72949NE, 72987NE

FSCA Identifier: RA-2016-12-02 Date:

Removal & Destruction of Affected Products Type of Action:

February 2017

ATTENTION: Clinical Personnel, Risk Managers, Biomedical Personnel

Description of the Problem

CareFusion has identified an issue with Back Check Valves Part Number 6122 & 6123 which are components in the following secondary sets:

72951NE - SECONDARY SET ONCOLOGY

72947NE - AMBER SECONDARY SET BCV

72948NE - Secondary set BCV, 0.2 micron filter


72949NE - SECONDARY SET WITH INTEGRATED SMART-SITE

72987NE - AMBER SECONDARY SET, VENTED, BCV

CareFusion has received reports of cracking of the secondary set back check valve male luer resulting in leakage of the infusion fluid. These secondary sets may be attached to a needle-free device that has been cleaned with a sanitising product containing IPA (Isopropyl Alcohol/PW 70%-30%) which appears to be contributing to the cracking of the plastic in this component.

1000RA00260 - Issue 1 Page 1 of 5





Potential Risk

Leakage at the back check valve connection could lead to the following effects:

- Unintentional Delays in start of infusion
- Exposure to chemicals
- Under infusion, without an alarm
- Infusion interruption.

Root Cause

Test performed on Part Number 6123 back check valves (6122 back check valves have the same core component as the 6123, but different caps) demonstrated that the IPA 70% can affect the Back Check Valve integrity which can lead to cracking resulting in leakage.

1000RA00260 - Issue 1 Page 2 of 5



Failure investigation was completed and during the investigation, it was possible to reproduce the failure within the first 5-10 seconds of reaction time, the investigation concluded that the material of the BCV 6123 (& 6122) component has low resistance to the IPA 70%, this finding was also confirmed by the supplier who also indicated that the material has limited alcohol resistance.

.

Products Potentially Affected

CareFusion has identified an issue with Back Check Valves Part Number 6122 & 6123 which are components in the following secondary sets:

72951NE - SECONDARY SET ONCOLOGY

Affected LOT numbers: 1000089, 1000129, 1000208, 1000468, 1000469, 1000687 & 1000713.

72947NE - AMBER SECONDARY SET BCV

Affected LOT numbers: 1000056, 1000118, 1000161, 1000470, 1000471, 1000784 & 1000858.

72948NE - Secondary set BCV, 0.2 micron filter Affected LOT numbers: 1000078.

72949NE - SECONDARY SET WITH INTEGRATED SMART-SITE Affected LOT numbers: 516641 & 517036.

72987NE - AMBER SECONDARY SET, VENTED, BCV

Affected LOT numbers: 520847.

Recommended Action Required

In order that the potentially affected products are removed from use and destroyed please follow instructions below:

Step	Action				
1	Inspect inventory for product affected lot numbers of 72951NE - SECONDARY SET ONCOLOGY, 72947NE - AMBER SECONDARY SET BCV, 72948NE - Secondary set BCV, 0.2 micron filter, 72949NE - SECONDARY SET WITH INTEGRATED SMART-SITE, 72987NE - AMBER SECONDARY SET, VENTED, BCV (listed above)				
	If	Then			
	No affected lot numbers are found	Complete sections A & B of Appendix 1			

1000RA00260 - Issue 1 Page 3 of 5



	Affected lot numbers are found	 Complete sections A & C of Appendix 1 Destroy affected product according to hospital protocol 					
2	Return completed verification form (Appendix 1) to your CareFusion representative no later than 22 June 2017						
3	Please contact your local products.	CareFusion representative to order alternative					

On receipt of the completed verification form Appendix 1, CareFusion will credit you for any product destroyed.

We sincerely apologise for any inconvenience this action may have caused you or your staff.

Should you have any questions or require assistance relating to this Field Safety Corrective Action, please contact your Local CareFusion representative.

Transmission of this Field Safety Notice

Please distribute this notice to all those who need to be aware of this action within your organisation.

Sincerely,

CareFusion Representative

1000RA00260 - Issue 1 Page 4 of 5



Via Email:

Appendix 1 - To be completed and returned by End User

URGENT FIELD SAFETY NOTICE – Acknowledgement Form

	OKOLIVITI	LLD SAILII NO	ITOL - ACKIN	wiedgement	OTT				
Product Name:		Secondary Sets containing Back Check Valve							
Product codes:		72951NE, 72947NE, 72948NE, 72949NE, 72987NE							
FSCA Identifi	er: I	RA-2016-12-02							
Date:	I	February 2017							
Type of Actio	Type of Action: Removal & Destr			Affected Pro	ducts				
Section A									
Name of Hos	pital / Facility	у							
Hospital / Fa	cility Address	5							
Telephone Nu	umber								
Name									
Signature									
Date									
I have read and understood the contents of this Field Action and confirm that our inventory has been checked and we have no inventory of the listed products. Section C I have read and understood the contents of this Field Action and confirm that our inventory has been checked and the following products have been destroyed:									
Batch Number	Quantity Destroyed		Quantity Destroyed	Batch Number	Quantity Destroyed				
1000056		1000208		1000713					
1000078		1000468		1000784					
1000089		1000469		1000858					
1000118		1000470		516641					
1000129		1000471		517036					
1000161		1000687		520847					
Please return no later than 22 June 2017 to: Local CareFusion Representative									
Address:									
Via Fax:									

1000RA00260 - Issue 1 Page 5 of 5