

Field Safety Notice Concerning the ERISMA LP EVO SCREW HEAD POSITIONER

11/05/2023 Clariance reference: 20230511_MV ANSM reference:

Dear Doctor, Vigilance Correspondent or Director of the establishment,

CLARIANCE has deemed it necessary to warn you of a risk linked to the disassembly of pedicle screw by using the "Screw Head Positioner" during surgery.

We bring to your attention the following information:

"We have detected a risk of disassembly of pedicle screw with the use of one of the instruments: the Screw Head Positioner (ref : 18719001, 18719002, 50719002).

This instrument is used to orientate and align the screw heads.

The risk assessment, based on our statistics prior to this incident, is a very low occurrence. In view of the latest tests carried out by our R&D department, we however feel it is necessary to inform all users of this risk.

Knowing that in such a case, the surgeon can use another instrument to orientate the screw head which is the Guiding Tube ref 18721005 or the Counter Torque ref 18721008 (both present in the Surgical Kit).

The root cause analysis has been completed. Preventive and corrective actions have been implemented to avoid the recurrence of the problem.

The risk for the patient is a loosening of the set screw which could migrate out of the screw head. In other words, there would be a loss of fixation stability, and therefore a loss of correction on at least one segment of the spine. This risk is limited by the symmetry of the assembly. What's more, the implants are biocompatible and radio-opaque. We have described the various possible cases of screw disassembly using the head positioner:

When the screw head is repositioned, the	No loosening of the set screw during post-operative
	inspection and normal monitoring. No or negligible impact on
	the stability of the assembly.
	The surgeon may notice disassembly if the Medical devices
	are removed during revision surgery.
	On post-operative and/or follow-up X-rays, the surgeon
	observes a partial loosening of the set screw. This affects the
disassemble the screw. The assembly is	stability of the assembly. The stem is free to translate on the
completed and held in place by the pressure	segment concerned. Depending on the patient's symptoms
of the rod and clamping screw.	(non-existent, pain, etc.) and the benefit/risk balance, the
	surgeon may decide to perform revision surgery.
	On post-operative and/or follow-up X-rays, the surgeon
	observes migration of the clamping screw. The set screw has
	come out of the screw head and no longer locks the stem.
	The stability of the assembly is affected. The stem is free on
of the rod and clamping screw.	the segment concerned.
	Depending on the patient's symptoms (no symptoms, pain,
	etc.) and the benefit/risk balance, the surgeon may decide to
	perform revision surgery.
	In addition to the situations described in cases 1, 2 and 3, the
	surgeon may observe one or more fragments on the pedicle
	screws on post-operative X-rays and subsequent follow-up X- rays, suggesting that a pin on the screw pad has migrated,
	breaking off as the pad moves and the stem rests on it.
or the rod and damping solew.	Depending on the patient's symptoms (no symptoms, pain,
	etc.), the benefit/risk balance for the patient and the area of
	migration of the fragment, the surgeon may decide to perform
	revision surgery.
	pad is removed from its position but does not disassemble the screw. The assembly is completed and held in place by the pressure of the rod and clamping screw. When the screw head is repositioned, the pad is removed from its position but does not disassemble the screw. The assembly is completed and held in place by the pressure



Pending a change in the design of the instrument to eliminate the risk and its replacement in the surgical KIT, you will find an appendix to the operating technique attached.

Please share this information within your Operating Room, Neurosurgery Department, Orthopedics Department, and any other function in your facility that needs to be aware of this FSN.

We remain at your disposal to provide you with any information that may help you.

To do so, please submit your request in writing to the Quality & Regulatory & Clinical Director to the following address: <u>m.hennequin@clariance-spine.com</u>

The ANSM has been notified of this safety information.

Please complete the attached form for our records, indicating that you have received this FSN and that it has been distributed within your institution.

We thank you in advance for your cooperation and we apologize for the inconvenience caused by this action.

Quality & Regulatory & Clinical Director



It is important that your institution confirm that you have received the FSN

Field Safety Notice Concerning the ERSMA LP EVO SCREW HEAD POSITIONER		
Reference FSN		
Date of FSN	11/05/2023	


□ We confirm that we have taken note of this safety notice		
Name of the establishment		
Address		
Name/Function		
Phone		
Date and signature		



Référence	Lot	Quantity
18719001	B104I	
	C611X	
	C856F	
	COOOF	
	D302F	
	D312F	
	D324F	
	G119 F	
	G704F	
	GA33F	
18719002	GA82F	
10110002		
	IB06Z	
	K725K	
	KC27K	
	M2D7K	
	MZDTR	
	M371K	
	MOAAK	
	M3A1K	
	N136K	
50740000	N180K	
50719002	I411U	



REPLACES p. 9 of 30BROENV02 Surgical Technique



If the screw is over-inserted or insufficiently inserted, its depth can be modified by using the T20 wrench.

Radiological control is carried out to verify the position of the screws in the pedicles.


Rod preparation



The Erisma®-LP Evolution system offers a range of pre-bent rods (30mm to 100mm). Longer rods are straight and require bending.

8

If desired, the guiding tube (1) or counter torque (2) may be used to orientate and align the screw heads.





Clariance 18 rue Robespierre 62217 Beaurains, France T+ 33 3 21 16 12 15