



[insert local affiliate or distributor address]

XX February, 2009

Urgent Field Safety Notice

Commercial Name of Affected Product:

30/40/50 CC IAB Catheters

30/40/50 CC IAB Volume Connectors

FSCA Identifier:

[Reference number assigned by National Competent Authority]

Type of action:

PRODUCT RECALL

AFFECTED PRODUCT CODES:

IAB-04830-U	IAB-04840-U	IAB-05840-U
IAB-05830-LWS	IAB-05830-U	IAB-05840-LWS
IAB-06830-U	IAB-06840-U	IAB-R950-U
IAB-S730C	IAB-S840C	IAK-02691
IAK-02692	IAK-02693	

This Field Safety Notice has been provided to you in English.
This notice will follow in your own language.

Dear Cardiac Care Customer,

1. Details on affected devices

Teleflex Medical, through its subsidiary Arrow International, has issued a voluntary recall for specific lots of the products identified above. The lot numbers affected are printed in Appendix A of this letter.

2. Description of the problem

Arrow International has become aware through a small number of customers that the blue connector for the 40cc IAB is not properly recognized by the Arrow Intra-Aortic Balloon Pump (IABP) system. A fault in the connector of the pump tubing assembly may result in the volume setting on the pump defaulting to 2.5 cc's or 5 cc's (depending on IABP model) rather than the appropriate 30, 40, or 50 cc volume.



If the incorrect volume is pumped and this is not recognized while IABP therapy is allowed to be continued at this volume, poor or no augmentation support will result, reducing the therapeutic efficacy and increasing the risk of ischemic events. Further, even in the presence of anticoagulation, the lack of movement of the IAB may increase the risk of thrombus development on the surface of the IAB. Therefore, Teleflex Medical, through its subsidiary Arrow International, has initiated a voluntary recall of these products. The Food and Drug Administration has been notified of this action.

3. Advise on action to be taken by Medical Staff

In order to provide the highest level of quality product to our customers, we are notifying our Customers to take the following action:

RECALL INSTRUCTIONS:

- Examine stock and quarantine all affected product immediately.
- Please print and complete the attached Recall Acknowledgement Form in Appendix C and fax back to Arrow Customer Services (number located on the form) who will contact you to arrange return of the product.
- Return any affected product freight collect, along with the original completed Recall Acknowledgement & Stock Status Form.
- Report all adverse incidents related to the affected products to the National Competent Authority and Teleflex Medical.

If you are a distributor, communicate this recall notice to your customers who received product within the scope of this recall by providing a copy of this recall notification to them. Also provide a copy of the Acknowledgement Form. This form should be completed in its entirety, signed and returned to you (the Distributor). As a Distributor, it is your responsibility to provide Teleflex Medical/Arrow International with a certification that all of your consignees have been contacted under this recall.

Or

MITIGATION DIRECTIONS:

For patients currently undergoing therapy please follow the mitigations described in Appendix B.

In circumstances where alternate IAB Catheters/adaptors or other forms of therapy are not available, contact Arrow International to obtain replacement tubing and implement the mitigations described in Appendix B until replacement Pump Tubing Assemblies are received. Arrow International will provide replacement Pump Tubing Assemblies within 7-10 days that will correct this potential defect. Replacement tubing can be ordered from Arrow International customer service by calling XXXXXX (Monday -Friday 8.30 -5.00pm) and request 30cc (Part Number IAK-02696), 40cc (Part Number IAK-02695), and 50cc (Part Number IAK-02693) Pump Tubing Assemblies.

Further information may be found at the company's website, www.arrowintl.com.



If you have any other questions, please feel free to contact your local sales representative or the Arrow International Customer Service, which is available at:

[insert local contact phone number here]

We strive to supply Cardiac Care Products of the highest quality and reliability. We regret any inconvenience caused by this issue and we thank you for your continued support.

4. Teleflex Medical/Arrow International Action

Teleflex Medical/Arrow International is notifying any potentially affected Customers, Teleflex Medical employees and Distributors of this Field Safety Notice.

5. Transmission of this Field Safety Notice

This notice should be passed on all persons who need to be aware within your organization or to any organization where the potentially affected devices have been transferred.

6. Contact reference person

Should you need any further information or support concerning this issue, please contact:

[insert local contact person name & details]

This recall is voluntary and all relevant Regulatory Agencies have been notified of this action. Teleflex Medical/Arrow International apologizes for any inconvenience caused by this issue.

Director, RA/QA
Kernen Facilities (Germany)

Attachments:

- Appendix A: Lot numbers affected by this recall
- Appendix B: Mitigation Directions
- Appendix C: Acknowledgement Form



APPENDIX A

ARROW INTERNATIONAL 30/40/50 CC IAB Catheters

LOT NUMBERS INCLUDED IN SCOPE OF RECALL

2009	
Product Number	Lot/Serial Number
IAB-04840-U	MF8124304
	MF9014426
	MF9014444
	MF9014446
	MF9014447
IAB-05830-LWS	MF8124308
	MF8124409
IAB-05830-U	MF8124064
	MF8124307
	MF8124408
IAB-05840-LWS	MF8124179
	MF8124202
	MF8124309
	MF8124340
	MF8124410
MF8124411	
IAB-05840-U	MF8124345
IAB-06830-U	MF8124413
	MF8124414
IAB-06840-U	MF8124162
IAB-R950-U	MF8124297
IAB-S730C	MF8124198
	MF8124282
IAB-S840C	MF8103165



2008	
Product Number	Lot/Serial Number
IAB-04830-U	MF6079580 MF6100954 MF7033668 MF7086558 MF7086984 MF7097225 MF7097426 MF7118000 MF7118001 MF7128557 MF8018922
IAB-04840-U	MF6090318 MF6111511 MF7065955 MF7076255 MF7086556 MF7097114 MF7097115 MF7097226 MF7097227 MF7097228 MF7097427 MF7097470 MF7097471 MF7107861 MF7107862 MF7118045 MF7118046 MF7128470 MF7128508 MF8018724 MF8018813 MF8018996 MF8124303 MF8124304
IAB-05830-LWS	MF6090321 MF6122057 MF7044419 MF7076250 MF7086674 MF7107863 MF7118002

2008	
	MF7128359
	MF7128561
	MF8018727
	MF8018849
	MF8019095
	MF8039848
	MF8039849
	MF8039991
	MF8040484
	MF8050805
	MF8050981
	MF8061206
	MF8061268
	MF8061335
	MF8061416
	MF8072073
	MF8082285
	MF8082394
	MF8082505
	MF8082506
	MF8092785
	MF8092999
	MF8103156
	MF8113922
	MF8114009
	MF8124160
IAB-05830-U	MF6122058
	MF7065640
	MF7076257
	MF7076378
	MF7097392
	MF7118003
	MF7118004
	MF7118219
	MF7128387
	MF7128471
	MF7128504
	MF7128505
	MF8018907
	MF8018997
	MF8030122
	MF8039664
	MF8039878
	MF8040324
	MF8040325

2008	
	MF8040638 MF8050911 MF8061125 MF8061176 MF8061334 MF8061500 MF8061615 MF8071782 MF8072074 MF8082267 MF8082584 MF8092783 MF8092784 MF8093000 MF8093001 MF8103155 MF8103262 MF8103263 MF8124064 MF8124178
IAB-05840-LWS	MF7044497 MF7054982 MF7076013 MF7086515 MF7086964 MF7097339 MF7097388 MF7107535 MF7128358 MF7128419 MF7128466 MF8018705 MF8018706 MF8018707 MF8018725 MF8018726 MF8018729 MF8018846 MF8018847 MF8018848 MF8018924 MF8018925 MF8018998 MF8018999 MF8019101

2008	
	MF8019102
	MF8029111
	MF8029166
	MF8029167
	MF8029168
	MF8029256
	MF8029257
	MF8029258
	MF8039704
	MF8039705
	MF8039706
	MF8039707
	MF8039709
	MF8040286
	MF8040326
	MF8040543
	MF8040641
	MF8050720
	MF8050721
	MF8050722
	MF8050806
	MF8050912
	MF8050913
	MF8050982
	MF8050995
	MF8050996
	MF8061126
	MF8061177
	MF8061185
	MF8061405
	MF8061406
	MF8061457
	MF8061501
	MF8071783
	MF8071784
	MF8071785
	MF8071786
	MF8071853
	MF8071854
	MF8071864
	MF8072072
	MF8082151
	MF8082395
	MF8082396
	MF8082397
	MF8092764

2008	
	MF8092786 MF8093003 MF8103157 MF8103158 MF8103640 MF8113837 MF8113838 MF8113839 MF8113840 MF8113949 MF8113950 MF8124161 MF8124179 MF8124202
IAB-05840-U	MF7065606 MF7076012 MF7076021 MF7086462 MF7086736 MF7107536 MF7107537 MF7107694 MF7107696 MF7118048 MF7118049 MF7118050 MF7118151 MF7118221 MF7118222 MF7128472 MF7128506 MF7128507 MF8018908 MF8019033 MF8019034 MF8019035 MF8019104 MF8029191 MF8029433 MF8029434 MF8039774 MF8040251 MF8040287 MF8050764 MF8050812

2008	
	MF8050966 MF8061267 MF8061413 MF8071676 MF8071863 MF8082268 MF8082507 MF8093002 MF8103280 MF8103416 MF8103571 MF8113836 MF8113919 MF8113951
IAB-06830-U	MF8039760 MF8039772 MF8040252 MF8040485 MF8040486 MF8040639 MF8050723 MF8050807 MF8050914 MF8061336 MF8061458 MF8061616 MF8061617 MF8071677 MF8071855 MF8082154 MF8082586 MF8092763 MF8093004 MF8103159 MF8103160 MF8103264 MF8103265 MF8103417 MF8124181 MF8124203
IAB-06840-U	MF8029428 MF8029506 MF8029508

2008	
	MF8030125 MF8030126 MF8039646 MF8039647 MF8039762 MF8039851 MF8040487 MF8040640 MF8050724 MF8061127 MF8061503 MF8071787 MF8072071 MF8082286 MF8082508 MF8093047 MF8103162 MF8103418 MF8103642 MF8113920 MF8114010 MF8124162
IAB-R950-U	MF7076413 MF7086743 MF7097191 MF8092738 MR8039844
IAB-S730C	MF7012650 MF7065398 MF7076011 MF7086585 MF7086981 MF7097060 MF7097473 MF7107623 MF7117871 MF7128553 MF8018756 MF8018814 MF8019001 MF8019036 MF8029114 MF8029190 MF8039773

2008	
	MF8039989 MF8040133 MF8050762 MF8050763 MF8050985 MF8051093 MF8061455 MF8071620 MF8082323 MF8082324 MF8082325 MF8092832 MF8103260 MF8124197 MF8124198
IAB-S840C	MF6090326 MF6101289 MF7012817 MF7065399 MF7065882 MF7076380 MF7086744 MF7097061 MF7097113 MF7097319 MF7097474 MF7118038 MF7118039 MF7128469 MF7128554 MF7128555 MF7128556 MF8018842 MF8018976 MF8019000 MF8019100 MF8029244 MF8029295 MF8029296 MF8029509 MF8039793 MF8039794 MF8039988 MF8040431 MF8040432



2008	
	MF8040433
	MF8040445
	MF8040601
	MF8040602
	MF8040603
	MF8050760
	MF8050761
	MF8050986
	MF8050987
	MF8050988
	MF8051091
	MF8051092
	MF8061324
	MF8061325
	MF8061456
	MF8071619
	MF8071627
	MF8071628
	MF8071789
	MF8071849
	MF8072043
	MF8082319
	MF8082320
	MF8082321
	MF8082322
	MF8092737
	MF8092833
	MF8092870
	MF8092871
	MF8092872
	MF8092873
	MF8103163
	MF8103164
	MF8103165
	MF8103166
	MF8103167
	MF8103168
	MF8103568
	MF8103569


APPENDIX B

ARROW INTERNATIONAL 30/40/50 CC IAB VOLUME CONNECTORS

MITIGATION DIRECTIONS

When setting up and using the unit follow all instructions in the Operator's Manual.

1. As stated in the Operator's Manual (See pages: 5-4 to 5-11 and 6-4 for ACAT1; 5-3 to 5-11 and 6-13 for AutoCAT 2 rev.2.21 and 5-3 to 5-11 and 6-13 for AutoCAT 2 rev 2.23.) this issue can be recognized immediately by verifying the VOLUME SETTING displayed on the screen of the ACAT 1 Plus and AutoCAT 2 Series IABP Console. The currently set volume of the IAB balloon pump catheter is shown in the Lower Right Area of the display, below the Hemodynamic values and above the HE tank bar graph. As soon as the IAB Volume connector is securely connected, the volume of the corresponding IAB catheter and connector should be properly displayed in the area shown. The IAB volume is also printed on the recorder strip.



When setting up the IABP console for use, ensure that the following steps are completed.


2. **Verify** that all connections are made properly. This includes the ECG cables, Arterial Pressure connections (AP) and the IAB volume connector. (See pages: 5-4 to 5-11 and 6-4 for ACAT1; 5-3 to 5-11 and 6-13 for AutoCAT 2 rev.2.21 and 5-3 to 5-11 and 6-13 for AutoCAT 2 rev.2.23).

3. **Verify** that after the IAB connector of the IAB pump tubing assembly is attached to the IABP console, the volume setting is correct for the corresponding connector that is listed below. The volume settings are as follows for the each color coded connector below:

- a. **White Connectors: 30cc**
- b. **Blue Connectors: 40 cc**
- c. **Orange Connectors: 50 cc**



4. If the volume is properly displayed, no further action is required. **Set the AUG Alarm (see section 8b below):** When the augmentation alarm is set and the Augmentation falls below the set limit, the IABP console will alert the clinician with an audible alarm and a screen message that states "AUG BELOW SET LIMIT". This alarm will alert the clinician when the level of augmentation is not being provided to the patient. If this alarm occurs, the clinician should assess the patient and the IABP and verify that the IAB volume setting is set to the correct level. The IAB volume, that is shown on the screen and recorder should be verified as per your hospital policy, but at least every 2 hours as described in the operator's manual.
5. If the volume is NOT properly displayed and reads 2.5cc on the AutoCAT 2 Series or 5.0cc on the ACAT 1 Series;
- a. **Disconnect and Reconnect the IAB Pump Tubing Assembly connector** making sure the IAB pump tubing assembly connector is fully seated in the receptacle.



- b. Verify the IAB volume setting on the IABP. If it is showing the correct volume, no further action is required.
6. If the IAB volume is still **INCORRECT**, you should replace the IAB Pump Tubing assembly with a tubing assembly of the same volume size.
 - a. **DISCONNECT** the IAB pump tubing assembly at the QUICK CONNECT on the balloon.
 - b. **REPLACE** with another appropriate size pump tubing assembly. Pump Tubing Assembly may be ordered from Arrow using 30cc (Part Number IAK-02696), 40cc (Part Number IAK-02695), and 50cc (Part Number IAK-02693).
 - c. **RECONNECT** to IABP and verify IAB volume setting is correct, as described above.

WARNING:

Use of an incorrectly sized IAB pump tubing assembly can result in under or over delivery of Helium to the IAB. This may reduce cardiac support or increase the risk of Helium embolism in the event of a leak in the IAB. This can also increase the risk of thrombus formation on the IAB balloon catheter that is implanted in the patient. If the thrombus formation is somehow dislodged from the catheter, it could potentially cause end organ damage or neurological deficits (i.e., stroke or transient ischemic attack).

Ensure that if an alternative pump tubing assembly is used, that it is the same volume as the pump tubing assembly that it is replacing.

7. If replacing the IAB pump tubing assembly with an assembly that does NOT correct the problem, change to another IABP console and notify your local Biomedical support staff or contact Teleflex Medical/Arrow IABP Worldwide Service.
8. Once pumping has been started:
 - a. **Assess** the AP waveform and note that Augmentation is present during IAB inflation. If the IAB volume is very low, Augmentation may not be present or may be very low. (See pages 5-14 to 5-18 and 9-15 to 9-18 for ACAT1; 6-16 to 6-18 and 8-20 to 8-22 for AutoCAT 2 rev.2.21; 6-18 and 8-24 to 8-26 for AutoCAT 2 rev2.23 for AP waveform/Timing assessment and assessment of augmentation).

- b. **Set the AUG Alarm:** The augmentation alarm when set will alert the clinician with an audible alarm and a screen message that states "AUG BELOW SET LIMIT". This alarm will alert the clinician that the proper augmentation/pressure is no being delivered to patient. To set the augmentation alarm:
- i. **Press AP SELECT**
 - ii. **Press AP Alarm**
 - iii. **TURN AP Alarm ON**
 - iv. **Verify AUG Alarm is selected**
 - v. **Set AUG AP Alarm to appropriate value based on patient condition and hospital protocol.**
 - vi. **See pages 10 to 11 for ACAT1; 3-33 to 3-34 for AutoCAT 2 rev.2.21 and 3-34 and 3-35 for AutoCAT 2 rev.2.23 for further information on the AP Alarm**
9. Refer to the operator's manual for proper operation of the IABP.



APPENDIX C

ARROW INTERNATIONAL 30/40/50 CC IAB VOLUME CONNECTORS
RECALL ACKNOWLEDGEMENT AND STOCK STATUS FORM

Immediate Attention Requested

Please check the appropriate box and return this form by Fax XXXXXX immediately.

- We have no inventory within the scope of this recall.
- We have the following affected product at our facility and have **discontinued use and distribution**. We have quarantined the affected product, and will return the following quantities.
- Due to lack of available product we have chosen to use the affected product and follow the mitigations described in Attachment B of the Recall Letter Dated: XX February 2009.

Return Authorization Number: _____

Contact Arrow Customer Service at **[insert local contact phone number]** for a Return Authorization Number.

(Print Name)

(Date)

(Signature)

(Telephone Number)

(Institution Name)

Alternate Mailing Address

(Institution Street Address)

(Street Address)

(Institution City, State, Zip)

(City, State, Zip)

(Country)

(Country)

All product details are to be completed on page 2 of this form.

Teleflex
MEDICAL

ARROW
INTERNATIONAL

QUANTITY

CATALOG NUMBER

LOT NUMBER