



Field Safety Notice

To: Laboratory Directors

From: Roche Diagnostics

Date: 11 May 2009

Re: AMPLILINK 3 Series Anomaly; Possible impact to Diagnostic and Blood screening results

Issue

Roche Molecular Diagnostics has become aware of a unique series of events involving the COBAS® AmpliPrep instrument running AMPLILINK software version 3.2.2 that results in specimens being amplified and detected with the wrong test parameters.

Investigation

A complaint was investigated in which specimens that were ordered to be tested for HBV were actually amplified and detected according to test parameters for HCV. The customer was using AMPLILINK 3.2.2 software on the COBAS® AmpliPrep / COBAS® TaqMan® 48 system.

The investigation determined that specimens to be tested for HBV and HCV viral levels were co-mingled on the same K carrier and subsequently all specimens were tested according to only the HCMCAP48 test definition file parameters.

The investigation determined this error can occur on either the COBAS® AmpliPrep / COBAS® TaqMan® 48, COBAS® AmpliPrep / COBAS® TaqMan® (docked) or **cobas** s 201 System (docked) running AMPLILINK Software versions 3.1 or 3.2 series up to and including version 3.2.2. The investigation determined that blood screening sites are not currently affected since all required conditions for the anomaly to occur do not exist.

The issue occurs only if all of the following events take place:

1. Configuration/Workflows using COBAS® AmpliPrep / COBAS® TaqMan® 48, COBAS® AmpliPrep / COBAS® TaqMan® (docked) or **cobas** s201 System (docked)
2. Two different test assays are being run on the same COBAS® AmpliPrep instrument where prepared specimens are placed on a K-Carrier
3. Partially filled Sample Racks are used
4. Specimens are blocked during the COBAS® AmpliPrep processing in the first sample rack (one or more specimens are unprocessed, due to insufficient reagents or disposables) resulting in the sample rack being mechanically "blocked" by the instrument (sample processing for remaining specimens is stopped) and a message occurs in case of insufficient reagent (i.e. level detection error). Other root causes for blocked samples (see print screen below) either do not permit a run to start or lead to a hardware message that stops the run (i.e. in case of insufficient consumables during a run).


Sample icon representation Each sample icon is labeled with a tube number, and is color-coded to indicate its status.

Icon	Condition	Explanation
	Position empty	No sample is loaded in this rack position. The tube number appears in black without a circle around it.
	Sample loaded	A sample is loaded in this rack position, but no order exists for the sample. Background color icon.
	Queued or Pending	An order was created and the sample is ready to be processed. White icon.
	In Process	Sample is currently being processed. Blue icon.
	Sample processed	Sample was successfully processed. Green icon.
	Flagged	Sample was fully processed but results have a flag in column Flags of the Results window (Sample Warning). Light green icon. Flags that generate a Sample Warning, are listed in <i>Flag priorities and status mappings of all flags</i> on page D-43
	Blocked	<u>Sample is blocked due to:</u> an order mismatch, insufficient reagents or consumables; sample volume error; clotted sample; missing tube. Yellow icon.
	Error or Aborted	Barcode error, tube handling error, or processing was stopped or cancelled. The results have a flag in column Flags in the Results window. Red icon.

Table A-35 Sample icons on Cassettes/Samples tab

5. The user resolves the root cause for the blocked samples (reload reagents or consumables) while the first sample rack is still blocked and the K carrier status is “finished”, indicating the processing of specimens initiated before the remaining samples were blocked is either almost complete or complete.
6. The first K-Carrier with the partially prepared batch needs to be removed (manually by the user via the K-Carrier Rack for the COBAS® TaqMan® 48 analyzer or automatically via the Docking Station for the COBAS® TaqMan® analyzer)
7. A new K-Carrier needs to be available (manually by the user via the K-Carrier Rack for COBAS® TaqMan® 48 analyzer or automatically via the Docking Station for the COBAS® TaqMan® analyzer)
8. A second sample rack is scheduled for processing, but is not fully loaded (short by at least the number of unprocessed samples on the first rack).
9. Steps 5 to 8 have to be done within a short time frame (~ 5 minutes) around the finishing time for the “unblocked” samples of the first sample rack (partially processed batch)

Decision tree for issue to happen



Detectability

The likelihood of the exact sequence and timing of events necessary to create the situation as outlined above is remote. However should this occur the detectability of the occurrence by the AMPLILINK software is not assured. At least one specimen will be flagged with the root cause (i.e. R_REAG_ERROR). Users may detect the occurrence by comparing the date time stamp for samples in the same batch when reviewing the Results in the rack view

Samples				Quality Control								
Rack ID	Date/Time	Batch ID	System ID	T	T #	Order/Lot Number	Sample ID	Test	Result	Flags	Date/Time	System ID
008	2/20/2009 12:47 PM	HBV 2 20.02.09	1275	S	01	* 0303064608	0303064608	HCMCAP48	Target Not Detected		2/20/2009 1:32:03 PM	391652
004	2/20/2009 10:52 AM	HCY 2 20.02.09	1475	S	02	* 0303065132	0303065132	HCMCAP48	Target Not Detected		2/20/2009 1:32:03 PM	391652
006	2/20/2009 9:22 AM	HBV 20.02.09	1475	S	03	* 0303065182	0303065182	HCMCAP48	Target Not Detected		2/20/2009 1:32:03 PM	391652
004	2/20/2009 9:07 AM	HBV 20.02.09	1475	S	04	* 0303065479	0303065479	HCMCAP48	217949 IU/mL		2/20/2009 1:32:03 PM	391652
006	2/19/2009 10:48 AM	HBV 19.02.09	1275	S	05	* 0303065491	0303065491	HCMCAP48	Target Not Detected		2/20/2009 1:32:03 PM	391652
005	2/19/2009 10:45 AM	HCY 19.02.09	1275	S	06	* 0303065789	0303065789	HCMCAP48	303437 IU/mL		2/20/2009 1:32:03 PM	391652
005	2/18/2009 10:55 AM	HCY 18.02.09	1475	S	07	* 0303065849	0303065849	HCMCAP48	693123 IU/mL	R_REAG_ERROR	2/20/2009 1:32:03 PM	391652
005	2/17/2009 11:31 AM	HBV 17.02.09	1275	S	08	* 0303066609	0303066609	HCMCAP48	476974 IU/mL		2/20/2009 2:58:16 PM	391652
005	2/17/2009 11:06 AM	HCY 17.02.09	1275	S	09	* 0303033372	0303033372	HCMCAP48	Target Not Detected		2/20/2009 2:58:16 PM	391652
005	2/16/2009 11:46 AM	HCY 16.02.09	1475	S	10	* 0303811144	0303811144	HCMCAP48	Target Not Detected		2/20/2009 2:58:16 PM	391652
006	1/22/2009 8:20 AM	HBV 02.01.09	1475	NC	11	* K101830000		HCMCAP48	Target Not Detected		2/20/2009 2:58:16 PM	391652

or in the Cyclor Batch view (specimen missing on first cyclor, mixed specimen on second cyclor).

Samples				Quality Control								
Rack ID	Date/Time	Batch ID	System ID	T	T #	Order/Lot Number	Sample ID	Test	Result	Flags	Date/Time	System ID
TCB_003	2/20/2009 2:02 PM	HBV 2 20.02.09	1275	S	07	* 0303065491	0303065491	HCMCAP48	Target Not Detected		2/20/2009 1:32:03 PM	391652
TCA_007	2/20/2009 12:21 PM	HCY 2 20.02.09	1275	S	08	* 0303065182	0303065182	HCMCAP48	Target Not Detected		2/20/2009 1:32:03 PM	391652
TCB_002	2/20/2009 11:35 AM	HBV 20.02.09	1475	S	12	* 0303064608	0303064608	HCMCAP48	Target Not Detected		2/20/2009 1:32:03 PM	391652
TCB_004	2/20/2009 10:33 AM	HBV 20.02.09	1475	S	13	* 0303065132	0303065132	HCMCAP48	Target Not Detected		2/20/2009 1:32:03 PM	391652
TCB_002	2/19/2009 12:33 PM	HBV 19.02.09	1275	S	16	* 0303065849	0303065849	HCMCAP48	693123 IU/mL	R_REAG_ERROR	2/20/2009 1:32:03 PM	391652
TCA_003	2/19/2009 12:12 PM	HCY 19.02.09	1275	S	17	* 0303065479	0303065479	HCMCAP48	217949 IU/mL		2/20/2009 1:32:03 PM	391652
TCA_004	2/18/2009 12:11 PM	HCY 18.02.09	1475	S	18	* 0303065789	0303065789	HCMCAP48	303437 IU/mL		2/20/2009 1:32:03 PM	391652
TCB_007	2/17/2009 1:06 PM	HBV 17.02.09	1275									
TCA_003	2/17/2009 12:34 PM	HCY 17.02.09	1275									
TCB_002	2/16/2009 12:46 PM	HCY 16.02.09	1475									

Samples				Quality Control								
Rack ID	Date/Time	Batch ID	System ID	T	T #	Order/Lot Number	Sample ID	Test	Result	Flags	Date/Time	System ID
TCB_003	2/20/2009 2:02 PM	HBV 2 20.02.09	1275	S	03	* 0303033376	0303033376	HBMCAP48	4436 IU/mL		2/20/2009 2:58:16 PM	391652
TCA_007	2/20/2009 12:21 PM	HCY 2 20.02.09	1275	S	07	* 0303065345	0303065345	HBMCAP48	Target Not Detected		2/20/2009 2:58:16 PM	391652
TCB_006	2/20/2009 11:55 AM	HCY 20.02.09	1475	S	08	* 0303811144	0303811144	HCMCAP48	Target Not Detected		2/20/2009 2:58:16 PM	391652
TCA_004	2/20/2009 10:16 AM	HCY 20.02.09	1475	S	09	* 309065692	309065692	HBMCAP48	100 IU/mL		2/20/2009 2:58:16 PM	391652
TCB_002	2/19/2009 12:33 PM	HBV 19.02.09	1275	S	11	* 309803368	309803368	HBMCAP48	< 15 IU/mL	S_BELOW_RANGE	2/20/2009 2:58:16 PM	391652
TCA_003	2/19/2009 12:12 PM	HCY 19.02.09	1275	S	12	* 0303066609	0303066609	HCMCAP48	476974 IU/mL		2/20/2009 2:58:16 PM	391652
TCA_004	2/18/2009 12:11 PM	HCY 18.02.09	1475	S	13	* 0303033372	0303033372	HCMCAP48	Target Not Detected		2/20/2009 2:58:16 PM	391652
TCB_007	2/17/2009 1:06 PM	HBV 17.02.09	1275	S	14	* 0303033374	0303033374	HBMCAP48	699 IU/mL		2/20/2009 2:58:16 PM	391652
TCA_003	2/17/2009 12:34 PM	HCY 17.02.09	1275	S	16	* 309065419	309065419	HBMCAP48	737 IU/mL		2/20/2009 2:58:16 PM	391652
TCA_002	2/16/2009 12:46 PM	HCY 16.02.09	1475	NC	17	* K101830000		HCMCAP48	Target Not Detected		2/20/2009 2:58:16 PM	391652
				S	18	* 309065419	0303065345	HBMCAP48	17776370 IU/mL		2/20/2009 2:58:16 PM	391652
				NC	22	* K113520000		HBMCAP48	Target Not Detected		2/20/2009 2:58:16 PM	391652

Prevention

The following measures will prevent the situation from occurring:

1. Do not load or unload any racks until the COBAS® AmpliPrep instrument run is finished when sample processing is blocked as described above.
2. Unload sample racks with unprepared/ blocked samples
3. Resolve issues reported by the software (i.e., reload reagent racks, load new reagent racks for unprepared/ blocked samples)
4. Create new batch (new order, control and rack) for remaining samples.

These steps should be followed until updated software is available.

Medical Impact

Due to the series of events that must take place, the likelihood of occurrence is exceedingly rare (1 of 7.7 million runs). As a result of this, it is unlikely that sequential specimens from the same patient would be affected. The COBAS® AmpliPrep COBAS® TaqMan® HCV, HBV, and HIV Tests are intended to be used as monitoring assays, it is unlikely that a physician would change a patient's treatment based on a single data point.

Corrective Actions

1. Due the rarity of occurrence and low risk of impacting a change in a patient's treatment, the overall risk is considered to be very low. However should you desire to conduct a review of previously generated test results, follow the above provided decision tree.
2. If the above outlined error is detected, all specimens are to be retested.
3. Until revised software is provided by Roche, follow the steps outlined above to prevent the possibility of generating erroneous results due to this anomaly.

Field Safety Notice: Affiliate Feed-Back Fax-Form

filled out by BA Safety Board

filled out by Local Safety Officer

Product Advisory Notice:

No: 003/ 2009

Date of issue: May 8, 2009

Affected product(s):

AMPLILINK 3 Series Anomaly with COBAS® AmpliPrep / COBAS® TaqMan® 48, COBAS® AmpliPrep / COBAS® TaqMan® (docked) or cobas s201 System (docked)

Subject:

Possibility of specimens being amplified and detected with the wrong test parameters

PAN from Business Area: send the filled out fax form back to:

Applied Science
(Fax: ++49 8856 60 3753)

Molecular Diagnostics
(Fax: ++1 925 730 8225)

Centralized Diagnostics
(Fax: ++49 621 759 6327)

Near Patient Testing
(Fax: ++43 316 27787 7490)

Diabetes Care
(Fax: ++49 621 759 3801)

Roche Diagnostic Ltd.
(Fax: ++41 41 798 5601)

RD Affiliate

Name of Local Safety Officer

--	--

Correction/removal was completed on:

Date (dd/mm/yy):	
------------------	--

