

Urgent Field Safety Notice

FSN-CPS-2019-004

CPS / ClinChem fully automated
Version 2
June-2019

BILD2 - Calibration and QC failures with reagent lots 33798101 and 35714101 on cobas c 701/702

Product Name	BILD2		
Product Description / GMMI	Bilirubin direct Gen.2	cobas c 701/702	05168384 190
Type of Action	Field Safety Corrective Action (FSCA)		

Dear Valued Customer,

Description of Situation

In the previous version of this FSN we communicated that Roche has received a number of complaints regarding Bilirubin direct Gen.2 (BILD2), reagent lot 33798101, on **cobas c** 701/702 modules. A low control recovery of BILD2 was observed immediately after cassette opening, with subsequent calibration of the affected cassette failing due to a Sens.E error. In recently performed investigations an additional affected lot 35714101 was identified.

To date, this issue has only been observed:

- in isolated cassettes
- with two specific reagent lots 33798101 and 35714101
- on **cobas c** 701/702 modules
- with additional color change of R2 in some but not all cases

Internal investigations with customer reagent returned to the manufacturer for analysis verified the issue. This issue can be clearly detected either by low control recovery or invalid calibration of the affected reagent cassette.

Negative deviations to an unknown extent were observed. This can lead to an underestimation of direct bilirubin in serum/plasma. In general, elevated conjugated bilirubin might point out at wider range of diseases and should lead to further medical testing. Most of the diseases with elevated direct bilirubin are associated with an elevation of liver enzymes, and/or clinical signs such as jaundice, scleral icterus. Measurement of conjugated bilirubin is used for diagnosis, monitoring and differential diagnosis of pre-hepatic, hepatic and post-hepatic jaundice. Considering the

BILD2 - Calibration and QC failures with of reagent lots 33798101 and 35714101 on cobas c 701/702

fact that the results should be interpreted in concordance with other parameters and examination findings, medical risk due to the issue is not probable, but cannot be excluded for patients at highest risk.

Actions taken by Roche Diagnostics

Comprehensive investigations have been done and are still ongoing. At this stage the root cause remains unknown. This field safety notification is being provided to customers preventively.

Actions to be taken by the customer/user

Workaround:

Each cassette of reagent lots 33798101 and 35714101 must be calibrated before use. If the calibration and/or QC recovery is out of specification the cassette must be discarded.

In this case, no general recommendations with respect to the review and follow up were given, taking into account different possible scenarios (e.g. detectability via QC might be given, failed calibration, error appearance). Any specific questions raised by the users should be addressed individually, considering all relevant clinical information.

Communication of this Field Safety Notice (if appropriate)

<If the recipient needs to forward the FSN to additional organizations/individuals then one or more of the following statements may be included:

This notice must be passed on to all those who need to be aware within your organization or to any organization/individual where the potentially affected devices have been distributed/supplied. (If appropriate).

Please transfer this notice to other organizations/individuals on which this action has an impact. (If appropriate).

Please maintain awareness of this notice and resulting action for an appropriate period to ensure the effectiveness of the corrective action. (If appropriate).

The following statement is mandatory in FSNs for EEA countries but is not required for the rest of the World:

Include if applicable: The undersigned confirms that this notice has been notified to the appropriate Regulatory Agency.

We apologize for any inconvenience this may cause and hope for your understanding and your support.

<closing salutations>,

Contact Details

To be completed locally:

Name

Title

Company Name

Address

Tel. +xx-xxx-xxxx xxxx

Email name@roche.com

BILD2 - Calibration and QC failures with of reagent lots 33798101 and 35714101 on cobas c 701/702