



Urgent Field Safety Notice Urgent Product Recall

Immediate Action Required

Date Issued October 2, 2023

Product

Product Description	List Number	Lot Number	UDI
IRON for use with ARCHITECT	6K95-41	30610Y600	(01)00380740010928(17)250131 (10)30610Y600
IRON for use with ARCHITECT	6K95-30	21058Y600	(01)00380740010911(17)241031 (10)21058Y600
IRON for use with ARCHITECT	6K95-30	21101Y600	(01)00380740010911(17)241031 (10)21101Y600
IRON for use with ARCHITECT	6K95-30	30918Y600	(01)00380740010911(17)250131 (10)30918Y600
Alinity c Iron Reagent Kit	08P3920	21118Y600	(01)00380740136253(17)241031 (10)21118Y600
Alinity c Iron Reagent Kit	08P3920	30227Y600	(01)00380740136253(17)241130 (10)30227Y600
Alinity c Iron Reagent Kit	08P3920	21046Y600	(01)00380740136253(17)240930 (10)21046Y600
Alinity c Iron Reagent Kit	08P3920	30302Y600	(01)00380740136253(17)241231 (10)30302Y600

Explanation

The purpose of this letter is to inform you that Sentinel CH SpA, the manufacturer of IRON for use with ARCHITECT and Alinity c Iron Reagent kit, has identified an issue with the reagents. Some customers have experienced elevated Quality Control (QC) results as well as elevated patient results.

Impact on Patient Results

Refer to attached Sentinel Field Safety Notice.

Necessary Actions to be Taken by Customer

Please review the attached Sentinel Field Safety Notice and follow the required actions.

- Complete and return the Abbott Customer Reply Form.
- Contact Abbott Customer Service for assistance if needed.
- If you have forwarded the product listed above to other laboratories, please inform them of this Product Recall and provide to them a copy of this letter.
- Please retain this letter for your laboratory records.

Contact Information

If you or any of the health care providers you serve have questions regarding this information, U.S. Customers please contact Customer Service at 1-877-4ABBOTT (available 24 hours a day, 7 days a week). Customers outside the U.S., please contact your local area Customer Service.

**Contact
Information**
continued

Adverse reactions or quality problems experienced with the use of this product may be reported to the FDA's MedWatch Adverse Event Reporting program online (<http://www.fda.gov/MedWatch/report.htm>), by phone (1-800-332-1088), or by fax (1-800-FDA0178).

If you have experienced any patient or user injury associated with this Field Action, please immediately report the event to your local area Customer Service.

**Field Safety Notice
Iron**

Product Name	Reference number REF	Lot Number	Expiration Date	UDI
IRON	6K95-41	30610Y600	2025-01-31	(01)00380740010928(17)250131 (10)30610Y600
IRON	6K95-30	21058Y600	2024-10-31	(01)00380740010911(17)241031 (10)21058Y600
		21101Y600	2024-10-31	(01)00380740010911(17)241031 (10)21101Y600
		30918Y600	2025-01-31	(01)00380740010911(17)250131 (10)30918Y600
Alinity c Iron Reagent Kit	08P3920	21046Y600	2024-09-30	(01)00380740136253(17)240930 (10)21046Y600
		21118Y600	2024-10-31	(01)00380740136253(17)241031 (10)21118Y600
		30227Y600	2024-11-30	(01)00380740136253(17)241130 (10)30227Y600
		30302Y600	2024-12-31	(01)00380740136253(17)241231 (10)30302Y600

SRN – Manufacturer
IT-MF-000012556

Date: September 29, 2023

Details on affected devices:

The purpose of this letter is to inform you of a product recall for IRON for use with ARCHITECT REF 6K95-41, REF 6K95-30 and Alinity c Iron Reagent Kit REF 08P3920. Sentinel has identified a performance issue for the reagent lots listed above. Please review the information below carefully and follow the necessary actions.

Description of the problem:

It has been identified that when using the ARCHITECT and Alinity c Iron products for the lots listed above, variable results can be obtained for quality control and patient samples. Based on internal testing, it has been confirmed that a positive shift of approximately 15% for Alinity c Iron products and approximately 30% for IRON for use with ARCHITECT products can be observed.

To date, no harm or injuries to patients have been reported with abnormal test results.

