

The angled air hose adapter GA508R is used as a connecting piece to angularly connect the air hose with the air motor. The angled air hose adapter is rotable on the motor as well as on the air hose.

The System is used for microsurgery, for neurological, spinal, oral and otolaryngological surgeries as well as in orthopedics. The motor can be applied with the angled adapter as well as without it.

Vorsitzender des Aufsichtsrates: Prof. Dr. h.c. Ludwig Georg Braun

Vorstand: Prof. Dr. Hanns-Peter Knaebel [Vorsitzender] Dr. Harald Stallforth (stelly. Vorsitzender) Dr. Joachim Schulz

Sitz der Gesellschaft: Tuttlingen Reg. Gericht: Stuttgart KRB 726261 USt. Id.-Nr. DEB12160059

WEEE-Reg.-Nr. DE 65109852

Bankverbindungen: Deutsche Bank AG Tuttlingen BLZ 653 700 75 Konto 21 22 000 00 IBAN DE44 6537 0075 0212 2000 00 78532 Tuttlingen SWIFT / BIC DEUTDESS653 Baden-Württembergische Bank BLZ 600 501 01 Konto 487 1905

Hausanschrift: Aesculap AG Am Aesculap-Platz Deutschland

. . .

## **BBRAUN**

page 2 Safety Information dated 16.10.2013

We received the information that during a surgery the AIR HOSE ADAPTER ANGLED F/AESCULAP SMALL, GA508R, disconnected from the motor, GA740R, on operation.

Due to the air pressure (up to 10 bar) the end of the air hose jerked upwards under application of pressure.

The root cause of the disconnection of the air hose adapter during surgery was the disassembling followed by the incorrect assembling of the angled air hose adapter in the hospital.

The lock washer of the adapter was deformed by the incorrect disassembling and assembling and therefore loosened, which caused the shifting of the bush. As a consequence of the shifting, the air hose adapter disconnected from the motor. Another potential consequence of the loosened lock washer and the shifted bush could be that the balls from the inside of the adapter could be freed and could fall out of the adapter.

## Caution: Potential risk of injury when incorrectly assembled!

- For the safe application of the product please comply with the instructions in the IFU.
- Please especially inspect the correct position of the lock washer. It has to be positioned free of play and in the first flute (fig. 1).




Figure 1: Position lock washer correct

Figure 2: Position lock washer incorrect

## BBRAUN

page 3 Safety Information dated 16.10.2013

Please make sure that any user of the above mentioned product and any other person that has to be informed within your organization, will take note of this safety information.

If you have forwarded the involved product to a third party, please provide a copy of this information to this party and also note Aesculap AG about this circumstance.

Please acknowledge the receipt of the safety information to :

Aesculap AG Dept. QMV Ms Kerstin Rothweiler Am Aesculap-Platz DE-78532 Tuttlingen

Tel.: + 49 7461 95-2182 Fax: + 49 7461 95-1555

kerstin.rothweiler@aesculap.de

p.p.

i p.p.



page 4 Safety Information dated 16.10.2013

Please complete this form and return to Ms Kerstin Rothweiler, Dept. QMV Fax: +49 7461-95 1555 E-mail: kerstin.rothweiler@aesculap.de

Ackowledgement	
<u>Safety Information</u> GA508R	
1. We acknowledge receipt of the safety information.	
2. Please mark accordingly:	
User:   User:   We have taken note of the safety information	on.
Retailer:	
We have forwarded the safety information to our customers and attach an according customer list.	
Facility Lo	cation
Name	
Department Te	I
Signature Da	ite