

Urgent FIELD SAFETY NOTICE

Device: **Terumo® CDI® Blood Parameter Monitoring System 500, BPM Sensor Head Assembly**

Reference: **FSN 1509 2016-04**

Action: **Removal**

Attention: Chief of Perfusion; Department of Cardiovascular Surgery; Director of Operating Room Services; Director of Biomedical Services; Risk Management

DESCRIPTION OF THE PROBLEM

Specific CDI® Blood Parameter Monitoring System 500 devices are being voluntarily recalled because the **Blood Parameter Module (BPM) Sensor Head Assembly's** Thermistor, which provides the blood temperature value that results in accurate display values on the monitor, does not meet specification. This may cause inaccurate temperature measurement and inaccurate analyte display values on the CDI System 500 monitor.

Terumo Cardiovascular Systems (Terumo CVS) received complaints of inaccurate temperature measurements for specific devices distributed since November 5, 2015. These include both new production devices and recently serviced devices.



DETAILS ON AFFECTED DEVICES

The affected population is limited to devices serviced or distributed from November 5, 2015 through February 3, 2016.

Refer to the exact Affected Population on the enclosed annex.

There are no other serial numbers involved.

Some of the CDI System 500 monitors from the list in annex can contain one BPM which is not impacted by this issue. Any BPM unit not listed in the table can be further used being not affected.

POTENTIAL HAZARD

A user who is not aware that the CDI System 500 is displaying inaccurate temperature values may not manage patient temperature appropriately. Using inaccurate information to manage warming and cooling strategies for a procedure could result in prolonged time on bypass. It could also lead to unnecessarily aggressive temperature management, resulting in excessive hyper or hypothermia, with potential neurologic and organ dysfunction, or increased blood component damage.

Inaccurate temperature measurement could also cause inaccurate measurements of other BPM values including potassium (K⁺), pO₂, pCO₂, and pH. The greater the temperature inaccuracy, the greater the degree of inaccuracy of these other BPM values due to the dependence of their algorithms on temperature for the calculations. Inaccurate measurement of these values could result in inappropriate patient management strategies being employed to address them with the potential to result in moderate patient injury.

It is likely that the user will recognize inaccurate temperature readings from the CDI System 500 due to the multiple temperature readings available from other devices in the operating room.

The CDI System 500 Instructions for Use caution the user to verify the accuracy of displayed values with another source before initiating treatment, as well as to perform periodic comparisons of results to a laboratory reference sample. Any question about the validity of a displayed value should prompt verification with another source (i.e. laboratory or blood gas analyzer).

It is important to note that HSAT monitoring functions are not affected by this issue (Hematocrit, Hemoglobin and Oxygen Saturation measures are not influenced by temperature measurement). Continued use of HSAT monitoring when using the CDI System 500 is clinically sound and offers patient benefit. It also may be included in hospital protocol or professional society care guidelines, or considered standard of care in some settings. Terumo CVS therefore recognizes the need to provide users the two options outlined below under corrective action.

CORRECTIVE ACTION

Depending on institution protocol or preference, users may choose to:


- Stop using devices with the affected serial numbers and return the affected devices to Terumo Europe, **or**
- Continue using devices with the affected serial numbers only for HSAT monitoring functions until the replacement BPM Sensor Head Assemblies are available.

See Customer Instructions for additional information.

Terumo Representatives will keep users updated as to timing of the correction and device availability.

CUSTOMER INSTRUCTIONS

1. Review this Field Safety Notice and assure that all users have received notice of this issue, and prominently display this notice where all users may access it.
2. Confirm receipt of this communication by completing and returning the attached Customer Response Form as indicated on the form.
3. Determine whether your institution will:
 - a) **Stop using devices with the affected serial numbers and return the affected devices to Terumo Europe.**
 - Terumo Europe will arrange the return of the device.
 - Terumo Europe will replace the BPM Sensor Head Assemblies in affected CDI System 500 devices and return the corrected devices to users after the correction is complete.
 - There is not yet a timing estimate on when the corrected BPM Sensor Head Assemblies will be available for replacement.
 - **OR** -
 - b) **Continue using devices with the affected serial numbers only for HSAT monitoring functions until the replacement BPM Sensor Head Assemblies are available.**
 - Attach the supplied label (see example below) to each affected BPM Sensor Head Assembly to indicate that it is no longer valid for clinical use.



Example label for affected BPM

- **It is essential that only the HSAT functionality be used** until either the impacted device is repaired or a loaner device is obtained, as these parameters are unaffected by temperature and therefore are immune to the issue which is the subject of this field action.
- Terumo Europe will contact users when the corrected component is available to request the affected devices be returned for service.


Either course of action may require the user to perform more frequent blood gas analysis from a laboratory or point-of-care blood gas analyzer.

Terumo Representatives will keep users updated as to timing of the correction and device availability.

We confirm that this *Field Safety Notice* has also been notified to your national Competent Authority.

We encourage you to contact us or your local Terumo representative with any questions or concerns.

Organisation (to be completed by the sales or dealer)
Contact name (function)
Contact phone, mobile, email



Terumo Europe NV
Leuven, Belgium

ANNEX - AFFECTED POPULATION

Affected BPM Serial number(s) mounted in affected CDI System 500 monitors

Some of the CDI System 500 monitors from the list below can contain one BPM which is not impacted by this issue. Any BPM not listed in the table below can be further used being not affected.

CDI500 Code	CDI500 Serial number	BPM Serial number	CDI500 Code	CDI500 Serial number	BPM Serial number
500AHCT	1137	B019851	500AVHCT	2243	B019969
500AHCT	1843	B021236	500AVHCT	2365	B021220
500AHCT	1997	B021266	500AVHCT	2374	B021234
500AHCT	2032	B021213	500AVHCT	2377	B020022
500AHCT	2207	B019871	500AVHCT	2377	B020023
500AHCT	2207	B021239	500AVHCT	2543	B021202
500AHCT	2717	B019807	500AVHCT	2543	B021211
500AHCT	2718	B021260	500AVHCT	2588	B019811
500AHCT	3059	B021131	500AVHCT	2601	B021147
500AHCT	3106	B021270	500AVHCT	2601	B021148
500AHCT	3187	B019941	500AVHCT	2629	B021144
500AHCT	3555	B021149	500AVHCT	2629	B021146
500AHCT	3556	B019791	500AVHCT	2669	B019850
500AHCT	3567	B021142	500AVHCT	2669	B020024
500AHCT	4004	B021237	500AVHCT	2757	B021134
500AHCT	5105	B021235	500AVHCT	2837	B019812
500AHCT	5151	B019848	500AVHCT	2837	B019813
500AHCT	5209	B019961	500AVHCT	2893	B021238
500AHCT	5266	B019971	500AVHCT	2980	B021132
500AHCT	5266	B020021	500AVHCT	3009	B021199
500AHCT	5709	B019889	500AVHCT	3010	B019967
500AHCT	5749	B021130	500AVHCT	3153	B019872
500AHCT	5750	B019849	500AVHCT	3182	B021267
500AHCT	5785	B021221	500AVHCT	3182	B021268
500AHCT	5788	B021215	500AVHCT	3390	B019810
500AHCT	7143	B021139	500AVHCT	3422	B019784
500AHCT	7260	B019890	500AVHCT	3422	B019885
500AVHCT	1052	B019959	500AVHCT	3422	B019886
500AVHCT	1052	B019960	500AVHCT	3605	B021145
500AVHCT	1052	B019968	500AVHCT	3607	B021261
500AVHCT	1427	B019884	500AVHCT	3607	B021262
500AVHCT	1697	B020020	500AVHCT	4099	B019808
500AVHCT	1697	B020025	500AVHCT	4099	B019809
500AVHCT	1857	B019887	500AVHCT	4262	B021133
500AVHCT	1857	B019888	500AVHCT	4344	B019869
500AVHCT	1903	B019970	500AVHCT	4344	B019870
500AVHCT	1928	B019783	500AVHCT	5242	B021141
500AVHCT	1958	B019814	500AVHCT	5520	B021201
500AVHCT	1970	B019957	500AVHCT	5520	B021264
500AVHCT	1972	B021259	500AVHCT	5520	B021265
500AVHCT	1984	B019939	500AVHCT	5762	B019790
500AVHCT	1984	B019940	500AVHCT	7250	B021219
500AVHCT	1984	B019958			

CDI500 Code	CDI500 Serial number	BPM Serial number	CDI500 Code	CDI500 Serial number	BPM Serial number
500AHCT	8004	All	500AHCT	8030	All
500AHCT	8005	All	500AHCT	8033	All
500AHCT	8014	All	500AHCT	8036	All
500AHCT	8015	All	500AHCT	8038	All
500AHCT	8017	All	500AHCT	8055	All
500AHCT	8019	All	500AVHCT	8022	All
500AHCT	8021	All	500AVHCT	8024	All
500AHCT	8025	All	500AVHCT	8037	All
500AHCT	8027	All	500AVHCT	8066	All
500AHCT	8029	All	500AVHCT	8067	All

Reference Device Code and Description

Catalog Number	Product Description
500AHCT	CDI Blood Parameter Monitoring System 500 With one blood parameter module and one Hct/Sat probe
500AVHCT	CDI Blood Parameter Monitoring System 500 With two blood parameter modules and one Hct/Sat probe

Field Safety Notice - CUSTOMER REPLY FORM

Device: **Terumo® CDI® Blood Parameter Monitoring System 500, BPM Sensor Head Assembly**

Reference: **FSN 1509 2016-04**

Action: **Removal**

Please complete, sign and e-mail or fax this back:

To:

E-mail/Telefax:

Client number	
Hospital Name	
City	
Country	

Our records indicate that you have received devices from the affected population.

By completion and return of this form, I am confirming receipt, reading and acting on this Safety Notice:

- We continue using devices with the affected serial numbers only for HSAT monitoring functions and we have attached the supplied label to the affected BPM Sensor Head Assembly to indicate that it is no longer valid for clinical use. We have labelled the following units:

CDI500 Code	Serial number - CDI500	Serial number (s) - BPM

- OR -

- We have stopped using the devices with the affected serial numbers and the following affected units ready to return:

CDI500 Code	Serial number - CDI500	Serial number (s) BPM	Number of units ready to return

Person Responding [Please Print]	
Title	
Phone Number	
Signature	
Date	

FSN1509A [EN]