

Advisory Notice

No.: MPG/QP35-01-20190704003

_____Agent:


Due to the operator's misoperation, an incorrect storage temperature upper limit was indicated on the label of the Dural Repair Patch sent to your company on June 21, 2019. The upper limit for the storage temperature should be 30°C, not 35°C. The correct label and the temperature information are shown as follows:


NeoDura™


REF : RDP-8 7.5cm×7.5cm (3 inch×3 inch)

LOT : 0202190309

SN : 021903090000

 Do Not Reuse

 Caution

 Do Not Resterilize



The temperature limit is 5°C to 30°C


Medprin Biotech GmbH
 Gutleutstraße 163-167, 60327 Frankfurt am Main, Germany
 Tel: +49-69-580059970 Fax: +49-69-580059971


CE 2797

Dural Repair Patch

1 piece


Sterile No.: 190314F5


 2022-03-08

 Do Not Use if Package is Damaged

 Consult Instructions for Use

STERILE R Sterilized Using Irradiation


 4 2 6 0 3 3 3 3 1 0 3 1 3


 (17) 220308 (10) 0202190309 (21) 021903090000

Correct (5°C-30°C)

Product information with incorrect labels is shown in the following table:

Product: Dural Repair Patch		PI No. PI19YZX06171B	Invoice No. MPG20190124
Lot number	Description	Q'ty	SN Number
202190226	RDP-4 4.0cm*6.0cm	8	021902260555-0562
0202190227	RDP-12 15.0cm*15.0cm	3	021902270290-0292



0202190310	RDP-7	6.0cm*8.0cm	5	021903100128-0132
0202190310	RDP-9	6.0cm*14.0cm	1	021903100155
0202190427	RDP-9	6.0cm*14.0cm	1	21904270103
0202190228	RDP-5	5.0cm*5.0cm	5	021902280181-185

Please be sure to store and transport the products at 5°C-30°C. This operation error does not affect the safety and effectiveness of our products.

If you have any questions, please contact us before July 31, 2019, so that we can handle the relevant issues.

Contact address: Gutleutstraße.163-167, 60327 Frankfurt am Main

Post No.: 60327

Contact person: Yuanyuan Li

Tel: +49-69-58005-9970, +86-20-32296118

E-mail: sales@medprin.com

Yours sincerely,

