

Teleflex Medical IDA Business & Technology Park Dublin Road, Athlone Co. Westmeath, Ireland

1<sup>st</sup> September 2016

## **URGENT FIELD SAFETY NOTICE**

Commercial Name of Affected Product:	EZIO Manual Driver		
Type of action:	Recall		
Teleflex Reference:	EIF-000066		
Product Code	Lot		
9025	4992333		
	5390069		
	5385261		

Dear Customer,

#### **Details of affected devices**

Teleflex has initiated a voluntary Field Safety Corrective Action for the above listed products.

### **Description of the problem**

Teleflex is recalling this product due to the absence of cleaning and disinfecting instructions in the current needle set IFU for the Manual Driver 9025 product. There is a very remote risk of the Manual Driver contaminating the intraosseous needle during use due to the absence of cleaning and disinfecting instructions.

Teleflex is recalling these lots in an effort to provide our customers and their patients with the highest quality product possible.



#### FIELD SAFETY CORRECTIVE ACTION INSTRUCTIONS

# ADVICE ON ACTION TO BE TAKEN BY MEDICAL STAFF

- We request that you check your inventory for product within the scope of this field action. Users should cease use and distribution of stock of affected product and quarantine immediately.
- 2. If you do not have stock in scope of this field action as referred to in above table then mark the according checkbox on the Acknowledgement form (Appendix 1) and return the form to the fax number or e-Mail-address mentioned there.
- 3. If you have stock from the affected product, mark the according checkbox on the Acknowledgement form (Appendix 1). Contact customer service by calling the phone number mentioned below, who will issue you with a return number. Write this return number into the respective field in the Acknowledgement form.
- 4. Complete 'Appendix 1' for all products in your possession and under control. Return this form immediately to the fax number below or provide a completed copy to your local Sales Representative.
- 5. Teleflex (or your local dealer) will issue a credit note upon receipt of the returned affected product.



#### INSTRUCTION FOR DISTRIBUTORS OF AFFECTED PRODUCT

- 1. If you are a distributor, provide this field safety notice to all of your customers who have received product in scope of this Field Action. Your customer is then required to complete the acknowledgement form and return this to you.
- As a Distributor you are required to confirm to Teleflex that you have completed the field activity outlined above. Upon completion of your actions, please forward the completed Acknowledgement Form to the fax number below.
- Please be aware that all European Economic Area/Switzerland (EEA/CH) and Turkey Member State Competent Authorities in which Teleflex distribute directly will be notified by Teleflex.
- 4. If you are a distributor and/or have a reporting responsibility within or outside the EEA/CH/TK area, please notify your local Competent Authority of this action. Please forward the notification and all communication with your local competent authority to Teleflex.

#### **Teleflex**

Teleflex informs all customers, employees of Teleflex and distributors on this Field Action.

### **Transmission of this Field Safety Notice**

This notice should be passed on all persons who need to be aware within your organization or to any organization where the potentially affected devices have been transferred. Please consider end users, clinicians, risk managers, supply chain/distribution centres etc. in the circulation of this notice.

Maintain awareness of this notice until all required actions have been completed in your organisation

## **Contact reference person**

Should you require any further information or support concerning this issue, please contact:

#### **Customer Service**

Contact: Herr Horst Erbe Telephone: 07151 / 406 – 431 Fax: +49 7151 / 406-566 e-mail: horst.erbe@teleflex.com

Teleflex is committed to providing high quality, safe and effective products. We sincerely apologize for any inconvenience this action may cause your operations. If you have any other questions, feel free to contact your local sales representative or Customer Service.

#### For and on behalf of Teleflex,





Appendix 1

# FIELD SAFETY CORRECTIVE ACTION

Teleflex Ref. EIF-000066

# **Acknowledgement Form**

# **URGENT ATTENTION REQUIRED**

Return completed form immediately to:

Fax: +49 7151 / 406-566 e-mail: horst.erbe@teleflex.com

Please check applicable box:				
completed the required actions contained therein. We confirm that our inventory does <b>NOT</b> include products affected by		We confirm receipt of this FSN and completed the required actions named therein. We confirm our inventory <b>DOES</b> include products ected by this Field Action. The use and further distribution of the affected ducts has been stopped. All products are on hold and the quantity ted below will be returned.		
	L	Return Autho	risation No	
Please CLEARLY print the below re	turn informa	tion		
Name of Affected Products		EZIO Manual Driver		
Product Number	Lot Number		Quantity (Returning)	
9025		4992333		
		5390069		
		5385261		
<ul> <li>Please label product returns as "F</li> <li>Include a copy of this form (includ Returns excluding ALL necessary documents)</li> <li>Institution Name - (Hospital, Health</li> </ul>	ng RAN Numl umentation C	ber) with product return ANNOT be processed		
Institution Address:		Email Address:		
_				
		Phone Number:		
Form completed by:				
Print Name :		Institution Stamp:		
Signature :				
Date:		1		
Dutc.				