



Jul-20

**Corrective action for SICOLAB mini ENDO,
only devices from the serial number list are affected.**

Dear Sir or Madam,

during our quality control it has been noticed that the coating on the surface can peel off in the interior of the pressure vessel. This can cause the pressure vessel to corrode over time. The function of the condensate drain valve cannot be guaranteed in the event of a fault.

Water may escape from the compressed air connection in devices that have the fault described above. Please take these devices out of operation immediately.

Up to now we do not know of any such event from the field with a SICOLAB mini ENDO. As the affected devices do not meet our requirements for safe products we will carry out a corrective measure.

The devices can be restored to a safe condition by replacing the affected components. Our staff will contact you to plan the implementation of the corrective measure.

With kind regards



List of serial numbers:

413700001
413700002
413700003
413700004
413700005
416645001
416645002
416645003
416645004
416645005
416749001
416749002
416749003
416749004
420379001
420380001