

Sample hospital

Your sign/message fromOur

signDial

Tel. 0521 807-Fax

0521 807-Date

29 November 2022

Important safety instructions for the Steelco washer-disinfectors PWD 8626 and PWD 8628

Dear Ladies and Gentlemen,

Herewith we want to inform you about a possible safety issue with the product type Steelco PWD 8626 and Steelco PWD 8628 manufactured by Miele & Cie. KG with the Intelligent cycle selection

According to our records, washer-disinfectors of these types are installed in your facility.

These units are equipped with an Intelligent cycle selection, that recognizes the load carriers and identifies the correct program for inserted devices.

With this letter we would like to inform you about a possible safety issue in connection with the Intelligent cycle selection. We are getting aware, that in a very few individual cases the inserted basket was not detected in a correct manner and a not optimal cycle was selected.

Each time you start the programme, even in the setting "automatic load recognition/Automatic programme allocation" we recommend that you check on the display of the unit whether the programme intended for the load carrier used has been started. If a wrong programme is displayed, interrupt the programme, and briefly pull the loading carrier out of the machine on the dirty side and then put it back into the machine. Then please switch off the "automatic load recognition/Automatic programme" setting and use the "direct

- 2 -

Miele & Cie. KG
Mielestraße 2
33611 Bielefeld
Phone: 0521 807-0
Fax: 0521 807-2090
AG Berlin
Internet:

company is a limited partnership with its registered office in Gütersloh,
-Ger. Gütersloh, HRA 3268. Pers. haft.
Verwaltungs-GmbH, Gütersloh, Reg.-Ger. Gütersloh, HRB 1325,
Verwaltungs-GmbH, Gütersloh, Reg.-Ger.

www.miele.de
Dr. Markus Miele, Rebecca Steinhage, Dr. Reinhard Zinkann.

Deutsche Bank AG Gütersloh
BIC: DEUTDE33HAN3333; BAN: DE34 4807 0040 0334 6780 00
Commerzbank AG Gütersloh
BIC: COBADE33HAN3333; IBAN: DE65 4784 0065 0151 2128 00
: Olaf Bartsch, Dr. Stefan Breit, Dr. Axel Kniehl, UniCredit Bank
BIC: HYVEDE33HAN3333; IBAN: DE41 1002 0890 0002 6688 58

operator's program choice and selection setting" (see instruction for use). You should also contact Miele or Steelco Service directly so that they can replace the faulty component.

This recommendation can be ignored, if your machine is operated by "direct operator's program choice and selection" or connected to an external batch documentation system which verifies the selected program with the intended program. In this context, for the purpose of completeness, we would like to remind you once again of the necessity of subjecting the reprocessing result to regular routine checks as well.

The service technician will check and replace the possible faulty component as a quality improving action during the next maintenance.

Please ensure in your organisation that all users of the above product and other persons to be informed are made aware of this safety notice. The competent authorities have been informed about this letter.

In addition, we require written feedback from you. Therefore, please complete and sign the enclosed reply form and return it to us by e-mail as a PDF scanned copy within two weeks of receipt.

-Your contact at Steelco –and also the recipient of your return is:

recipient: Mr. Endriu Lago (Steelco Regulatory Affairs manager)

e-mail: service-hq@steelcogroup.com

We apologise for any inconvenience caused and will be happy to answer any questions you may have.

We remains at your disposal and thank you for your cooperation.

Miele & Cie. KG
Regulatory Affairs Officer

