



22. June 2020

**Important: FOR IMMEDIATE REVIEW - 3M PRODUCT NOTIFICATION**

Affected Product: 3M™ Transbond™ Plus Light Cure Adhesive Kit  
Catalog#: 712-080  
Lot#: JS8EH

Attn: Orthodontists

Dear Valued 3M Customer:

During a recent quality investigation, 3M discovered that Lot #JS8EH of the 3M™ Transbond Plus Light Cure Band Adhesive Kit, Catalog #712-080 may contain the incorrect adhesive model. The packaging is labeled as Transbond Plus Light Cure Band Adhesive Kit, Catalog #712-080, but may incorrectly contain Transbond XT Light Cure Adhesive Syringes. Because customers may be receiving a product with different features than ordered, 3M is notifying customers about this matter.

There is no immediate risk to patient health. The Transbond XT Light Cure Adhesives syringes are labeled correctly and readily identifiable from Transbond Plus Light Cure Adhesive. In addition, there are obvious differences between the two adhesives including color, thickness, flow, dispensing method and disposable tip making it unlikely the product would be dispensed. Bond strength specifications of the two adhesives are identical.

**Action Required:**

Our records indicate you have received the affected lot:

Catalog #	Lot Number
712-080	JS8EH

The kit may contain the XT adhesive by mistake. We recommend monitoring band seating during regular treatment controls to ensure continued bonding integrity.

If you wish to return product, please contact the 3M Customer Service at [3MUnitekGermany@mmm.com](mailto:3MUnitekGermany@mmm.com) to arrange for a Return Goods Authorization number to

facilitate the return of the impacted product to 3M. Once 3M has received the impacted product your account will be issued credit or sent replacement product.

We appreciate your assistance and apologize for any inconvenience this situation may cause you.

Sincerely,

