



URGENT FIELD SAFETY NOTICE

GE Healthcare

9900 Innovation Drive
Wauwatosa, WI 53226
USA

<Date of Letter Deployment>

GEHC Ref# 60885

To: Hospital Administrators / Risk Managers
Radiology Department Managers
Radiologists

RE: **MR Surgical Suite II Table Transfer Release**

GE Healthcare has recently become aware of a potential safety issue with the table transfer release of the MR Surgical Suite II MR system. **Please ensure that all potential users in your facility are made aware of this safety notification and the recommended actions.**

Safety Issue The issue may cause an unexpected function loss of the patient transfer mechanism that allows the patient to be moved between the MR and surgical tables. This could delay care and handling of a patient during surgical or interventional procedures. GE has received one complaint of a transfer board not releasing from the MR table preventing the transfer board from moving to the surgical table. There have been no injuries reported as a result of this issue.


Safety Instructions You may continue to use the table. Monitor for any issues in releasing the table. If you see this issue, contact a GE Field Engineer.

Affected Product Details MR Surgical Suite Option, model numbers M8074SS, M8053SS, and M0074SS.


Product Correction GE Healthcare will correct all affected products at no cost to you. A GE Healthcare representative will contact you to arrange for the correction.

Please be assured that maintaining a high level of safety and quality is our highest priority. If you have any questions, please contact us immediately per the contact information above.

Sincerely,



Vice President - Quality & Regulatory
GE Healthcare



Chief Medical Officer – Medical Solutions
GE Healthcare