

DATE:

**Notice of RECALL – URGENT**

TO: CooperSurgical “Arch Style” Uterine Manipulation Customers  
 RE: VIGILANCE of CooperSurgical UMH700 and early versions of the UMH750 uterine manipulation handles.

Dear Valued International Customer,

CooperSurgical is voluntarily recalling the UMH700 (RUMI ARCH®) and certain versions of the UMH750 (Advincula Arch™) Handles. The UMH700 was obsoleted earlier this year and superseded with the Advincula Arch UMH750 handle.



**Reason for this Field Action:**

Excessive pressure exerted on the uterine tip when attached to the Arch may, under certain circumstances, cause the internal steel rod of the tip to protrude through the cleaning hole on the shaft of the handle.

**Devices Affected by this Recall:**

Part Number	Product Description	Details
UMH700	RUMI ARCH	<b>EVERY</b> Handle needs to be returned
UMH750	Advincula Arch	<b>Only</b> handles with a serial number less than 1204001, or between 11110010 and 11110069 need to be returned.

Our records indicate that one or more of these devices have been shipped to you. **Please make contact with all of your customers who have these handles** and get them replaced as soon as possible.

Please contact our Customer Service Department at 203-601-9818. At the first prompt press “1.” At the second prompt press “1” again. Arrangements will be made to replace product in your possession at CooperSurgical’s expense. Further instructions and disposition of product will be communicated directly to you at that time. Furthermore, we would appreciate it greatly if you would please fill out the attached “Request for Replacement of Recalled Product” form and fax it to CooperSurgical, Inc., Attention International Customer Service at 1-203-601-4747.

CooperSurgical deeply regrets the inconvenience that this problem has caused.

Sincerely,



Vice President, Regulatory Affairs and Business Assurance