

TO WHOM IT MAY CONCERN

Your reference

Our reference

Tel. +49/56 61/71-

Fax +49/56 61/71-

Date

August 28, 2013

Discofix C, Recall of one batch as a preventive measure

REF: 16494C

LOT: 13H0892042

Dear Sirs,

In the course of internal quality checks we have found that with a low probability of occurrence this stopcock may leak due to an injection molding issue. Therefore we have decided to recall the concerned batch as a preventive measure.

Our records show that your hospital has received Discofix C from this specific batch. Please do not use devices of this batch and send them back to us.

Please forward this information to the users within your hospital immediately.

A replacement has already been initiated.

Please accept our apologies for any inconveniences.

We kindly ask you to confirm the receipt of this information. Should you have any questions, please call your local B. Braun contact person under Tel xxx-xxxx.

Yours sincerely,

Chairman of Supervisory Board:

Prof. Dr. h.c. Ludwig Georg Braun

Executive Board:

Prof. Dr. Heinz-Walter Große
(Chairman)
Dr. Annette Beller
Otto Philipp Braun

Prof. Dr. Hanns-Peter Kriebel
Dr. Meinrad Lugan
Caroll H. Neubauer, LL.M.
Markus Strotmann
(Deputy member)

Corporate Office: Melsungen

Register Court: Local Court Fritzlar
HRB 11 000
WEEE-Reg.-No. DE 42690900

Address:

B. Braun Melsungen AG
Carl-Braun-Straße 1
34212 Melsungen
Germany