

TO WHOM IT MAY CONCERN

Your reference

Our reference

Tel. +49/56 61/71-

Fax +49/56 61/71-

Date

April 27, 2015

Infusomat Space Line UV-Protect, Recall of several batches as a preventive measure

Infusomat Space Line, TRANSP,UV-PROT,PUR,LL,250CM, REF: 8700127SP

Batches: 14M17F00H2, 14M22F00H2, 14M26F00H2, 14N03F00H2, 14N04F00H2

Infusomat Space Line, Y-PORT,UV-PROT,PUR,LL,250CM, REF: 8250437SP

Batch: 14N17F00H2

Dear Sirs,

In the course of internal quality checks we have found that with a low probability of occurrence these Infusomat Space Lines may leak due to an assembly issue at the tubing connection to the drip chamber. Therefore we have decided to recall the concerned batches as a preventive measure.

Our records show that your hospital has received **Infusomat Space Line UV-Protect** sets from the specific batches.

Please do not use devices of these batches and send them back to us. For replacement please contact our local sales team.

Please forward this information to the users within your hospital immediately.

Please accept our apologies for any inconveniences.

We kindly ask you to confirm the receipt of this information. Should you have any questions, please call your local B. Braun contact person under Tel xxx-xxxx.

Yours sincerely,

Chairman of Supervisory Board:

Prof. Dr. h.c. Ludwig Georg Braun

Executive Board:

Prof. Dr. Heinz-Walter Große

(Chairman)

Dr. Annette Beller

Otto Philipp Braun

Prof. Dr. Hanns-Peter Knaebel

Dr. Meinrad Lugin

Caroll H. Neubauer, LL.M.

Markus Strotmann

Corporate Office: Melsungen

Register Court: Local Court Fritzlar

HRB 11 000

WEEE-Reg.-No. DE 42690900

Address:

B. Braun Melsungen AG

Carl-Braun-Straße 1

34212 Melsungen

Germany