

GE Healthcare, Surgery
384 Wright Brothers Drive
Salt Lake City, Utah 84116
U.S.A.

CFMI 15033 International

URGENT RECALL NOTICE

PLEASE TAKE ACTION TO INFORM ALL USERS OF THE RELEVANT SYSTEM(S) OF THESE ISSUES AND HOW TO ADDRESS THEM

April 24, 2008

**To: Hospital Administrator
 Director/Manager of Radiology**

Subject: Product Safety Issues

**Affected Products: OEC UroView 2800, OEC 9800 Plus, OEC MiniView 6800, OEC
 FlexiView 8800 Mobile C-Arm**

Our records indicate that your facility has one or more of the following GE Healthcare OEC (GEHC OEC) devices:

- OEC UroView 2800
- OEC 9800 Plus
- OEC MiniView 6800
- OEC FlexiView 8800 Mobile C-Arm

GEHC OEC has discovered an issue where some GE OEC Fluoroscopy systems may not have had some mounting brackets properly grounded to the chassis which may result in non-compliance to EN/IEC 60601-1.

Your GE OEC Field Service Engineer will be contacting your facility to arrange an inspection of your GEHC OEC system to assure that the brackets are properly grounded to the system chassis.

If you have any questions or concerns regarding these issues, please do not hesitate to contact the service team for further information at 800-874-7378 option 8. Information is available at this number 24 hours per day, 7 days a week.

Thank you,

[REDACTED]

[REDACTED]

President and CEO

GE Healthcare Surgery