



URGENT

MEDICAL DEVICE RECALL NOTIFICATION

SAMPLE LETTER

December 11, 2006

Product: ConMed Linvatec UltraPower® and E9000® Bur Products, Sterile, Single-use in Pouches (packaged one per box)

Catalog and Lot Numbers: See Attached Listing of Affected Catalog and Lot Numbers

Attention: International Distributor/Sales Representative

Our distribution records indicate your facility received one or more of the attached catalog numbers and lots of ConMed Linvatec UltraPower® and/or E9000® Bur Products, Sterile, Single-use in Pouches (packaged one per box). The company has determined there is a possibility that the product pouch package of certain catalog numbers and lots of burs may not be completely sealed, thereby potentially compromising the sterility of the devices. It has been determined that this issue was caused by the sealing operation, which may result in an open seal or a void in the seal. This recall is being conducted to the distributor and user level. Please do not use or distribute the product.

We are requesting that you assist us in collecting the product in your inventory including affected product in the possession of your sales force. Please perform the following immediately upon receipt of this notification. We have attached a listing of product that was distributed to your account and sales force to assist you in this action.

1. Please check your facility's inventory **immediately**, including affected product in the possession of your sales force for the product catalog numbers and lots in the attached list. Notify your sales force of the recall and collect all affected catalog numbers and lots of product from your sales force.
2. You are requested to return to ConMed Linvatec, for a no-charge replacement, all of the listed catalog numbers and lots of product that were distributed to your account.
3. Mail or fax the REPLY FORM to the address provided on the form. Return the product by Federal Express Collect using ConMed Linvatec Account Number 033608306. Please include the REPLY FORM with your return. Note: No credit will be issued if you certify that your facility has no affected product in inventory.
4. If you have sold the product to a customer we are requesting that you issue the enclosed International Customer letter to the customer immediately upon receipt of this notification. Please collect the product from your customers, complete the REPLY FORMS and return them to ConMed Linvatec, Largo, FL.
5. If your facility does not have any of the affected catalog and lot numbers (specified in the attached listing) in inventory, please complete the REPLY FORM and mail or fax the form to ConMed Linvatec.

Please accept our sincere apology for any inconvenience this action may have caused. Should you have any additional questions, please contact me at 727-399-██████████ or fax at 727-399-██████████ or customer service at ██████████, email at ██████████@linvatec.com

Sincerely,

██████████
██████████

Recall Coordinator
ConMed Linvatec, USA



**URGENT
MEDICAL DEVICE RECALL NOTIFICATION**


Product: ConMed Linvatec UltraPower[®] and E9000[®] Bur Products,
Sterile, Single-use in Pouches (packaged one per box)

PRODUCT POUCH SEAL INSPECTION PROCEDURE INSTRUCTIONS

(To be performed by trained ConMed Linvatec Representatives only)



1. Collect all of the affected recalled product that was distributed to the account.
2. Prior to opening any product for inspection, clear the area of any other products. Only one lot of product should be present in the inspection area at any time.
3. Open the white folding carton box and remove the product.
4. Inspect each product pouch for any open seal and/or pouch material slightly folded on itself (creased) as shown in the photographs in the opposite side of this instruction sheet.
5. Document all inspections and results on the Product Inspection and Reply Form for each account.
6. Reject/remove any pouches found with an open seal and/or pouch material slightly folded (creased).
7. Only those pouch seals with **NO** open seal and/or pouch material slightly folded (creased) are acceptable for use. If inspection of the pouch is acceptable, replace the product into the box. This product can be returned to inventory for use.
8. If inspection of any pouch finds the pouch to be **not acceptable**, collect the product for return to ConMed Linvatec, Largo, FL per instructions in the ConMed Linvatec Medical Device Recall Notification letters.
9. Any product that is not sealed or is suspect of not being sealed needs to be returned to ConMed Linvatec, Largo, FL.
10. Collect and return, to ConMed Linvatec, Largo, FL, all rejected product and provide a no-charge replacement product to the account.
11. Complete the Product Inspection and Reply Form documenting the units inspected and results for each catalog number and lot of product collected for inspection. Sign and date the form. **Your customer MUST also sign the form.**
12. Mail or fax the Product Inspection and Reply Form to [REDACTED] at ConMed Linvatec, 11311 Concept Blvd., Largo, Florida 33773. Fax 1-727-399-5264).
13. Return the product by Federal Express Collect using ConMed Linvatec Account Number 033608306. Reference RG No. U2006.
14. Please include the Product Inspection and Reply Form with your return to ConMed Linvatec, Largo, FL.
15. If your customer does not have any of the affected catalog and lot numbers in inventory, please have them complete the Product Inspection and Reply Form and mail or fax the form to [REDACTED] at ConMed Linvatec, 11311 Concept Blvd., Largo, Florida 33773. Fax 1-727-399-5264

Reference: ConMed Linvatec Quality Management Procedure QAP-817, Rev. AA, "Product Pouch Seal Inspection Procedure"



Good Seal

**Crease
(Fold over)**



**Crease
(Fold over)**



MEDICAL DEVICE RECALL NOTIFICATION
REPLY FORM
(Return to ConMed Linvatec Distributor)

FROM:

Date

Product: ConMed Linvatec UltraPower® and E9000® Bur Products, Sterile, Single-use in Pouches (packaged one per box)
Catalog Number: See Attached Listing of Affected Catalog Numbers
Lot Number(s): See Attached Listing of Affected Lot Numbers

International Customer Notification
ConMed Linvatec RG Number: U2006

CHECK/TICK:

_____ I verify that our facility or sales force does not have any of the affected catalog numbers or lots of ConMed Linvatec UltraPower® and/or E9000® Bur Products, Sterile, Single-use in Pouches.

_____ The following ConMed Linvatec UltraPower® and/or E9000® Bur(s) will be returned for Replacement: (Please attach additional sheets if necessary.)

Catalog Number _____ Lot Number _____ Number of Devices _____

Catalog Number _____ Lot Number _____ Number of Devices _____

Catalog Number _____ Lot Number _____ Number of Devices _____

Catalog Number _____ Lot Number _____ Number of Devices _____

Catalog Number _____ Lot Number _____ Number of Devices _____

Signature

Title

Date

Printed Name

Telephone

Fax

Please return the completed REPLY FORM and product to:

ConMed Linvatec
International Distributor

RG No. U2006

ConMed Linvatec Product Removal Report- UltraPower and E9000 Bur Products -List of Affected Products, Lot Numbers, Manufacturing Dates, and Quantites Manufactured

UltraPower Part Numbers	CATALOG NUMBER	LOT NO.
00702101800	00702101800	BBC59297
00702101800 Count		1
00702104100	00702104100	BBC59841
00702104100	00702104100	BBC61790
00702104100	00702104100	BBC62809
00702104100	00702104100	BBC63425
00702104100	00702104100	BBC64236
00702104100 Count		5
00702104200	00702104200	BBC63722
00702104200 Count		1
00702104300	00702104300	BBC69049
00702104300 Count		1
00702106200	00702106200	BBC64240
00702106200 Count		1
00702107700	00702107700	BBC64950
00702107700 Count		1
00702108300	00702108300	BBC58456
00702108300 Count		1
00702109500	00702109500	BBC58541
00702109500	00702109500	BBC59435
00702109500	00702109500	BBC65287
00702109500 Count		3
00702112700	00702112700	BBC63815
00702112700 Count		1
00702112800	00702112800	BBC58831
00702112800	00702112800	BBC65804
00702112800 Count		2
00702112900	00702112900	BBC58537
00702112900	00702112900	BBC62855
00702112900	00702112900	BBC66189
00702112900	00702112900	BBC71308
00702112900 Count		4
00702114100	00702114100	BBC59776
00702114100	00702114100	BBC60951
00702114100	00702114100	BBC62685
00702114100	00702114100	BBC63585
00702114100	00702114100	BBC64220
00702114100	00702114100	BBC68919
00702114100	00702114100	BBC70275
00702114100 Count		7
00702114150	00702114150	BBC61861
00702114150	00702114150	BBC63738
00702114150 Count		2
00702114300	00702114300	BBC64651
00702114300 Count		1
00702118100	00702118100	BBC62145
00702118100	00702118100	BBC65292
00702118100 Count		2
00702119500	00702119500	BBC59532
00702119500 Count		1
00702120600	00702120600	BBC69244
00702120600 Count		1
00702121400	00702121400	BBC59773
00702121400 Count		1
00702122700	00702122700	BBC61507
00702122700 Count		1
00702122800	00702122800	BBC58677
00702122800	00702122800	BBC60260
00702122800	00702122800	BBC61189
00702122800	00702122800	BBC62649
00702122800	00702122800	BBC63446

ConMed Linvatec Product Removal Report- UltraPower and E9000 Bur Products -List of Affected Products, Lot Numbers, Manufacturing Dates, and Quantites Manufactured

00702122800	00702122800	BBC65362	
00702122800 Count			6
00702122900	00702122900	BBC58802	
00702122900	00702122900	BBC62854	
00702122900	00702122900	BBC63620	
00702122900	00702122900	BBC65729	
00702122900	00702122900	BBC67796	
00702122900	00702122900	BBC71249	
00702122900 Count			6
00702123000	00702123000	BBC70000	
00702123000 Count			1
00702123600	00702123600	BBC66460	
00702123600 Count			1
00702123700	00702123700	BBC61508	
00702123700	00702123700	BBC63612	
00702123700	00702123700	BBC66207	
00702123700 Count			3
00702125000	00702125000	BBC61828	
00702125000 Count			1
00702126400	00702126400	BBC62308	
00702126400	00702126400	BBC63605	
00702126400	00702126400	BBC64627	
00702126400 Count			3
00702127100	00702127100	BBC64783	
00702127100 Count			1
00702127400	00702127400	BBC62817	
00702127400 Count			1
00702127500	00702127500	BBC60952	
00702127500	00702127500	BBC62635	
00702127500	00702127500	BBC64878	
00702127500 Count			3
00702128300	00702128300	BBC59295	
00702128300	00702128300	BBC60442	
00702128300 Count			2
00702129100	00702129100	BBC63971	
00702129100 Count			1
00702129400	00702129400	BBC58540	
00702129400	00702129400	BBC66147	
00702129400	00702129400	BBC66208	
00702129400 Count			3
00702130300	00702130300	BBC55938	
00702130300	00702130300	BBC63614	
00702130300	00702130300	BBC67520	
00702130300 Count			3
00702130900	00702130900	BBC58832	
00702130900 Count			1
00702131800	00702131800	BBC61778	
00702131800	00702131800	BBC64415	
00702131800 Count			2
00702132400	00702132400	BBC61731	
00702132400 Count			1
00702132500	00702132500	BBC65498	
00702132500 Count			1
00702132600	00702132600	BBC61730	
00702132600 Count			1
00702132700	00702132700	BBC59440	
00702132700 Count			1
00702132800	00702132800	BBC57192	
00702132800	00702132800	BBC61168	
00702132800	00702132800	BBC62670	
00702132800	00702132800	BBC63450	
00702132800	00702132800	BBC65370	
00702132800	00702132800	BBC66215	
00702132800 Count			6
00702132900	00702132900	BBC63250	

ConMed Linvatec Product Removal Report- UltraPower and E9000 Bur Products -List of Affected Products, Lot Numbers, Manufacturing Dates, and Quantites Manufactured

00702132900	00702132900	BBC65803
00702132900	00702132900	BBC66197
00702132900 Count		3
00702133700	00702133700	BBC61191
00702133700	00702133700	BBC62674
00702133700	00702133700	BBC63535
00702133700	00702133700	BBC65179
00702133700	00702133700	BBC65711
00702133700	00702133700	BBC66462
00702133700	00702133700	BBC68784
00702133700 Count		7
00702136200	00702136200	BBC64373
00702136200 Count		1
00702136300	00702136300	BBC61826
00702136300 Count		1
00702136500	00702136500	BBC57187
00702136500	00702136500	BBC62815
00702136500	00702136500	BBC65128
00702136500	00702136500	BBC65802
00702136500 Count		4
00702136600	00702136600	BBC63966
00702136600 Count		1
00702137100	00702137100	BBC59164
00702137100 Count		1
00702137400	00702137400	BBC62816
00702137400 Count		1
00702137500	00702137500	BBC62820
00702137500	00702137500	BBC63646
00702137500	00702137500	BBC64352
00702137500 Count		3
00702138200	00702138200	BBC63280
00702138200	00702138200	BBC65814
00702138200 Count		2
00702139500	00702139500	BBC62834
00702139500 Count		1
00702139600	00702139600	BBC65291
00702139600 Count		1
00702171300	00702171300	BBC58764
00702171300	00702171300	BBC60262
00702171300	00702171300	BBC62013
00702171300	00702171300	BBC62958
00702171300	00702171300	BBC63337
00702171300	00702171300	BBC65655
00702171300	00702171300	BBC66145
00702171300	00702171300	BBC68619
00702171300 Count		8
00702181500	00702181500	BBC58099
00702181500	00702181500	BBC58262
00702181500	00702181500	BBC58338
00702181500	00702181500	BBC58382
00702181500	00702181500	BBC60985
00702181500	00702181500	BBC60987
00702181500	00702181500	BBC61186
00702181500	00702181500	BBC61187
00702181500	00702181500	BBC61380
00702181500	00702181500	BBC61443
00702181500	00702181500	BBC61454
00702181500	00702181500	BBC61484
00702181500	00702181500	BBC61808
00702181500	00702181500	BBC61809
00702181500	00702181500	BBC61811
00702181500	00702181500	BBC61817
00702181500	00702181500	BBC61827
00702181500	00702181500	BBC61843
00702181500	00702181500	BBC61850

ConMed Linvatec Product Removal Report- UltraPower and E9000 Bur Products -List of Affected Products, Lot Numbers, Manufacturing Dates, and Quantites Manufactured

00702181500	00702181500	BBC62100
00702181500	00702181500	BBC62104
00702181500	00702181500	BBC62105
00702181500	00702181500	BBC62110
00702181500	00702181500	BBC62133
00702181500	00702181500	BBC62134
00702181500	00702181500	BBC62260
00702181500	00702181500	BBC62268
00702181500	00702181500	BBC62269
00702181500	00702181500	BBC62270
00702181500	00702181500	BBC62318
00702181500	00702181500	BBC62321
00702181500	00702181500	BBC62322
00702181500	00702181500	BBC62339
00702181500	00702181500	BBC62477
00702181500	00702181500	BBC62480
00702181500	00702181500	BBC62483
00702181500	00702181500	BBC62498
00702181500	00702181500	BBC62504
00702181500	00702181500	BBC62505
00702181500	00702181500	BBC62507
00702181500	00702181500	BBC62598
00702181500	00702181500	BBC62599
00702181500	00702181500	BBC62666
00702181500	00702181500	BBC62668
00702181500	00702181500	BBC62669
00702181500	00702181500	BBC62675
00702181500	00702181500	BBC62676
00702181500	00702181500	BBC62677
00702181500	00702181500	BBC62776
00702181500	00702181500	BBC62801
00702181500	00702181500	BBC62802
00702181500	00702181500	BBC62803
00702181500	00702181500	BBC62804
00702181500	00702181500	BBC62852
00702181500	00702181500	BBC62883
00702181500	00702181500	BBC62884
00702181500	00702181500	BBC62910
00702181500	00702181500	BBC62911
00702181500	00702181500	BBC63054
00702181500	00702181500	BBC63055
00702181500	00702181500	BBC63058
00702181500	00702181500	BBC63066
00702181500	00702181500	BBC63072
00702181500	00702181500	BBC63076
00702181500	00702181500	BBC63079
00702181500	00702181500	BBC63102
00702181500	00702181500	BBC63133
00702181500	00702181500	BBC63188
00702181500	00702181500	BBC63189
00702181500	00702181500	BBC63248
00702181500	00702181500	BBC63249
00702181500	00702181500	BBC63380
00702181500	00702181500	BBC67443
00702181500	00702181500	BBC67446
00702181500	00702181500	BBC67957
00702181500	00702181500	BBC68019
00702181500	00702181500	BBC68065
00702181500	00702181500	BBC69217
00702181500	00702181500	BBC69219
00702181500	00702181500	BBC69333
00702181500	00702181500	BBC69668
00702181500	00702181500	BBC69711
00702181500	00702181500	BBC71773

ConMed Linvatec Product Removal Report- UltraPower and E9000 Bur Products -List of Affected Products, Lot Numbers, Manufacturing Dates, and Quantites Manufactured

00702181500 Count		83
00702191700	00702191700	BBC58673
00702191700	00702191700	BBC59681
00702191700	00702191700	BBC61509
00702191700	00702191700	BBC64441
00702191700	00702191700	BBC66679
00702191700 Count		5

Number of catalogs 55
Number of lots 207

ConMed Linvatec Product Removal Report - ConMed Linvatec UltraPower and E9000 Bur Products
 List of Affected Products, Lot Numbers, Manufacturing Dates, and Quantities Manufactured

E9000 PART NUMBER	CATALOG NUMBER	LOT NO
M30-900-217	E4217	BBC59906
M30-900-217 Count		1
M30-900-300	E8030LSO	BBC57965
M30-900-300	E8030LSO	BBC62833
M30-900-300	E8030LSO	BBC66572
M30-900-300 Count		3
M30-900-305	E8040LSO	BBC62297
M30-900-305	E8040LSO	BBC62652
M30-900-305	E8040LSO	BBC65474
M30-900-305	E8040LSO	BBC66134
M30-900-305 Count		4
M30-900-310	E8050LSO	BBC60970
M30-900-310	E8050LSO	BBC62307
M30-900-310	E8050LSO	BBC63059
M30-900-310	E8050LSO	BBC66068
M30-900-310	E8050LSO	BBC66076
M30-900-310 Count		5
M30-900-315	E8065LSO	BBC57880
M30-900-315	E8065LSO	BBC60973
M30-900-315	E8065LSO	BBC62011
M30-900-315	E8065LSO	BBC62111
M30-900-315	E8065LSO	BBC63061
M30-900-315	E8065LSO	BBC65733
M30-900-315	E8065LSO	BBC66425
M30-900-315 Count		7
M30-900-320	E8130LSO	BBC60586
M30-900-320	E8130LSO	BBC61378
M30-900-320	E8130LSO	BBC62115
M30-900-320	E8130LSO	BBC64250
M30-900-320	E8130LSO	BBC65685
M30-900-320	E8130LSO	BBC65901
M30-900-320	E8130LSO	BBC66591
M30-900-320 Count		7
M30-900-325	E8140LSO	BBC58988
M30-900-325	E8140LSO	BBC59531
M30-900-325	E8140LSO	BBC61503
M30-900-325	E8140LSO	BBC62298
M30-900-325	E8140LSO	BBC62384
M30-900-325	E8140LSO	BBC63062
M30-900-325	E8140LSO	BBC65479
M30-900-325	E8140LSO	BBC66135
M30-900-325 Count		8
M30-900-330	E8150LSO	BBC58716
M30-900-330	E8150LSO	BBC59429
M30-900-330	E8150LSO	BBC60594
M30-900-330	E8150LSO	BBC62302
M30-900-330	E8150LSO	BBC63060
M30-900-330	E8150LSO	BBC63534
M30-900-330	E8150LSO	BBC65554
M30-900-330	E8150LSO	BBC65559
M30-900-330 Count		8
M30-900-335	E8165LSO	BBC58337
M30-900-335	E8165LSO	BBC60777
M30-900-335	E8165LSO	BBC61493
M30-900-335	E8165LSO	BBC62650
M30-900-335	E8165LSO	BBC63449
M30-900-335	E8165LSO	BBC64442
M30-900-335	E8165LSO	BBC65759
M30-900-335	E8165LSO	BBC66383
M30-900-335 Count		8
M30-900-336	E8265LSO	BBC65993

M30-900-336 Count		1
M30-900-340	E8230LSO	BBC59153
M30-900-340	E8230LSO	BBC59817
M30-900-340	E8230LSO	BBC61379
M30-900-340	E8230LSO	BBC62112
M30-900-340	E8230LSO	BBC62957
M30-900-340	E8230LSO	BBC63097
M30-900-340	E8230LSO	BBC65677
M30-900-340	E8230LSO	BBC65903
M30-900-340	E8230LSO	BBC66568
M30-900-340 Count		9
M30-900-345	E8240LSO	BBC58643
M30-900-345	E8240LSO	BBC59022
M30-900-345	E8240LSO	BBC59972
M30-900-345	E8240LSO	BBC61505
M30-900-345	E8240LSO	BBC62824
M30-900-345	E8240LSO	BBC62923
M30-900-345	E8240LSO	BBC63816
M30-900-345	E8240LSO	BBC65480
M30-900-345	E8240LSO	BBC66352
M30-900-345 Count		9
M30-900-346	E8540LSO	BBC57966
M30-900-346 Count		1
M30-900-350	E8250LSO	BBC58737
M30-900-350	E8250LSO	BBC61732
M30-900-350	E8250LSO	BBC62826
M30-900-350	E8250LSO	BBC63095
M30-900-350	E8250LSO	BBC66364
M30-900-350 Count		5
M30-900-355	E8530LSO	BBC58250
M30-900-355 Count		1
M30-901-015	E8020	BBC57800
M30-901-015 Count		1
M30-901-035	E8210	BBC58628
M30-901-035	E8210	BBC59679
M30-901-035	E8210	BBC62009
M30-901-035	E8210	BBC65202
M30-901-035 Count		4
M30-901-040	E8215	BBC63592
M30-901-040	E8215	BBC64881
M30-901-040 Count		2
M30-901-045	E8220	BBC58257
M30-901-045	E8220	BBC60956
M30-901-045	E8220	BBC62018
M30-901-045	E8220	BBC62316
M30-901-045	E8220	BBC63033
M30-901-045	E8220	BBC63527
M30-901-045	E8220	BBC63760
M30-901-045	E8220	BBC64525
M30-901-045	E8220	BBC64784
M30-901-045	E8220	BBC65055
M30-901-045	E8220	BBC65295
M30-901-045	E8220	BBC65893
M30-901-045	E8220	BBC66648
M30-901-045 Count		13
M30-901-046	E8520	BBC59775
M30-901-046 Count		1
M30-901-050	E8225	BBC59678
M30-901-050	E8225	BBC64425
M30-901-050	E8225	BBC66649
M30-901-050 Count		3
M30-901-080	E8115	BBC67171
M30-901-080 Count		1
M30-901-090	E8125	BBC57749
M30-901-090	E8125	BBC58256

M30-901-090 Count		2
M30-902-000	E6040	BBC59748
M30-902-000 Count		1
M30-902-005	E6140	BBC58642
M30-902-005	E6140	BBC59778
M30-902-005	E6140	BBC61748
M30-902-005	E6140	BBC63590
M30-902-005	E6140	BBC63991
M30-902-005	E6140	BBC64634
M30-902-005	E6140	BBC65050
M30-902-005 Count		7
M30-902-010	E6150	BBC58632
M30-902-010	E6150	BBC61767
M30-902-010	E6150	BBC62143
M30-902-010	E6150	BBC62499
M30-902-010	E6150	BBC63601
M30-902-010	E6150	BBC64064
M30-902-010	E6150	BBC64628
M30-902-010	E6150	BBC65201
M30-902-010 Count		8
M30-902-015	E6160	BBC58797
M30-902-015 Count		1
M30-902-030	E6210	BBC59533
M30-902-030	E6210	BBC59771
M30-902-030	E6210	BBC60505
M30-902-030	E6210	BBC61829
M30-902-030	E6210	BBC61925
M30-902-030	E6210	BBC62876
M30-902-030	E6210	BBC63868
M30-902-030	E6210	BBC64629
M30-902-030	E6210	BBC65043
M30-902-030	E6210	BBC65927
M30-902-030	E6210	BBC66616
M30-902-030 Count		11
M30-902-035	E6215	BBC58733
M30-902-035	E6215	BBC60409
M30-902-035	E6215	BBC61712
M30-902-035	E6215	BBC62012
M30-902-035	E6215	BBC62878
M30-902-035	E6215	BBC63515
M30-902-035	E6215	BBC64414
M30-902-035	E6215	BBC64787
M30-902-035	E6215	BBC65053
M30-902-035	E6215	BBC65882
M30-902-035	E6215	BBC66617
M30-902-035 Count		11
M30-902-040	E6220	BBC58789
M30-902-040	E6220	BBC61366
M30-902-040	E6220	BBC62014
M30-902-040	E6220	BBC63034
M30-902-040	E6220	BBC63429
M30-902-040	E6220	BBC64000
M30-902-040	E6220	BBC64455
M30-902-040	E6220	BBC64789
M30-902-040	E6220	BBC65041
M30-902-040	E6220	BBC65301
M30-902-040	E6220	BBC65892
M30-902-040	E6220	BBC66631
M30-902-040 Count		12
M30-902-041	E6520	BBC60357
M30-902-041 Count		1
M30-902-045	E6230	BBC59907
M30-902-045	E6230	BBC60507
M30-902-045	E6230	BBC61101
M30-902-045	E6230	BBC62017

M30-902-045	E6230	BBC62124
M30-902-045	E6230	BBC63428
M30-902-045	E6230	BBC63761
M30-902-045	E6230	BBC64229
M30-902-045	E6230	BBC64522
M30-902-045	E6230	BBC65146
M30-902-045	E6230	BBC65298
M30-902-045	E6230	BBC66594
M30-902-045 Count		12
M30-902-046	E6530	BBC57967
M30-902-046 Count		1
M30-902-050	E6240	BBC58627
M30-902-050	E6240	BBC59165
M30-902-050	E6240	BBC60958
M30-902-050	E6240	BBC61953
M30-902-050	E6240	BBC62317
M30-902-050	E6240	BBC63651
M30-902-050	E6240	BBC64458
M30-902-050	E6240	BBC64795
M30-902-050	E6240	BBC65145
M30-902-050	E6240	BBC65895
M30-902-050 Count		10
M30-902-055	E6250	BBC57769
M30-902-055	E6250	BBC60795
M30-902-055	E6250	BBC61830
M30-902-055	E6250	BBC62007
M30-902-055	E6250	BBC62126
M30-902-055	E6250	BBC64791
M30-902-055	E6250	BBC65147
M30-902-055 Count		7
M30-902-060	E6225	BBC67170
M30-902-060 Count		1
M30-902-065	E6105	BBC59890
M30-902-065 Count		1
M30-902-070	E6110	BBC57968
M30-902-070 Count		1
M30-902-075	E6115	BBC60058
M30-902-075 Count		1
M30-902-080	E6120	BBC66862
M30-902-080 Count		1
M30-902-085	E6125	BBC58202
M30-902-085 Count		1
M30-902-090	E6130	BBC59889
M30-902-090	E6130	BBC67494
M30-902-090 Count		2
M30-903-010	E5210	BBC59870
M30-903-010	E5210	BBC60410
M30-903-010	E5210	BBC61922
M30-903-010	E5210	BBC62501
M30-903-010 Count		4
M30-903-015	E5215	BBC62879
M30-903-015 Count		1
M30-903-020	E5220	BBC59749
M30-903-020	E5220	BBC59908
M30-903-020	E5220	BBC61706
M30-903-020	E5220	BBC62727
M30-903-020	E5220	BBC63845
M30-903-020	E5220	BBC65889
M30-903-020 Count		6
M30-903-025	E5230	BBC59909
M30-903-025	E5230	BBC60413
M30-903-025	E5230	BBC61679
M30-903-025	E5230	BBC62123
M30-903-025	E5230	BBC62881
M30-903-025	E5230	BBC63763

M30-903-025	E5230	BBC64654
M30-903-025	E5230	BBC65148
M30-903-025	E5230	BBC65930
M30-903-025 Count		9
M30-903-030	E5240	BBC60754
M30-903-030	E5240	BBC63857
M30-903-030	E5240	BBC64616
M30-903-030	E5240	BBC65051
M30-903-030	E5240	BBC65296
M30-903-030 Count		5
M30-903-050	E5160	BBC59884
M30-903-050	E5160	BBC65994
M30-903-050 Count		2
M30-903-055	E5140	BBC60307
M30-903-055 Count		1
M30-903-060	E5150	BBC66861
M30-903-060 Count		1

Number of catalogs 50
 Number of lots 223